

Mr. Reed Timko
Grinnell Fire Protection Systems Company
835 Sharon Drive
Westlake, OH 44145

February 23, 1999

Dear Mr. Timko:

Based on the information and test data submitted in your application dated July 20, 1998, with enclosures thereto, we conclude that the Lo-Pro Series 612I and 912I smoke detectors are acceptable for licensing purposes in accordance with the conditions of the enclosed registration certificate (NR-0776-D-102E).

As you requested that MF Series smoke detector registration certificate be transferred to inactive status by the fact these devices are no longer manufactured and distributed by Grinnell Fire Protection Systems Company and Grinnell Fire Protection Systems Company does not have any intention to produce them in the future. New registration number is NR-0-776-D-801-E. Copies of the certificates have been forwarded to the appropriate reviewer for licensing action.

Please be advised that you must manufacture and distribute the product in accordance with the statements and representations contained in your application, with enclosures thereto, and the information set out in your registration certificate. As a general rule, you must request and obtain an amendment to the certificate before you make changes or modifications to the information submitted to obtain the certificate.

Please read over the registration certificate in its entirety and notify us immediately of any errors or omissions.

You are obligated to notify us promptly in writing should you decide to no longer manufacture or offer service support for the product.

Please be aware that, as a holder of an NRC registration, you may be subject to the NRC's licensing and inspection fees in accordance with 10 CFR Part 170, and annual fees in accordance with 10 CFR Part 171. If you have any questions concerning the fee requirements, please contact the License Fee and Debt Collection Branch at (301) 415-7544.

If you have any questions, please contact me at (301) 415-5787 or Mr. John Jankovich at (301) 415-7904.

Sincerely,

/s/
Seung J. Lee, Mechanical Engineer
Materials Safety Branch
Division of Industrial and
Medical Nuclear Safety
Office of Nuclear Material Safety
and Safeguards

Enclosure: As stated
cc w/encl: SKimberley, LFDCB

Distribution:

MSB r/f IMNS r/f SSD-98-81 NE01 *JK* SSD File # NR-0776-D-102-E
DOCUMENT NAME: C:\SJL\NR776101.CMP

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	MSB	E	MSB	E					
NAME	SLee <i>SL</i>		JJankovich <i>JP</i>						
DATE	02/16/99		02/18/99						

COPY

Mr. Reed Timko
 Grinnell Fire Protection Systems Company
 835 Sharon Drive
 Westlake, OH 44145

February 23, 1999

Dear Mr. Timko:

Based on the information and test data submitted in your application dated July 20, 1998, with enclosures thereto, we conclude that the Lo-Pro Series 612I and 912I smoke detectors are acceptable for licensing purposes in accordance with the conditions of the enclosed registration certificate (NR-0776-D-102E).

As you requested that MF Series smoke detector registration certificate be transferred to inactive status by the fact these devices are no longer manufactured and distributed by Grinnell Fire Protection Systems Company and Grinnell Fire Protection Systems Company does not have any intention to produce them in the future. New registration number is NR-0-776-D-801-E. Copies of the certificates have been forwarded to the appropriate reviewer for licensing action.

Please be advised that you must manufacture and distribute the product in accordance with the statements and representations contained in your application, with enclosures thereto, and the information set out in your registration certificate. As a general rule, you must request and obtain an amendment to the certificate before you make changes or modifications to the information submitted to obtain the certificate.

Please read over the registration certificate in its entirety and notify us immediately of any errors or omissions.

You are obligated to notify us promptly in writing should you decide to no longer manufacture or offer service support for the product.

Please be aware that, as a holder of an NRC registration, you may be subject to the NRC's licensing and inspection fees in accordance with 10 CFR Part 170, and annual fees in accordance with 10 CFR Part 171. If you have any questions concerning the fee requirements, please contact the License Fee and Debt Collection Branch at (301) 415-7544.

If you have any questions, please contact me at (301) 415-5787 or Mr. John Jankovich at (301) 415-7904.

Sincerely,

/s/
 Seung J. Lee, Mechanical Engineer
 Materials Safety Branch
 Division of Industrial and
 Medical Nuclear Safety
 Office of Nuclear Material Safety
 and Safeguards

Enclosure: As stated
 cc w/encl: SKimberley, LFDCB

Distribution:

MSB r/f IMNS r/f SSD-98-81 NE01 *JK* SSD File # NR-0776-D-102-E

DOCUMENT NAME: C:\SJL\NR776101.CMP

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	MSB	<input checked="" type="checkbox"/> E	MSB	<input checked="" type="checkbox"/> E					
NAME	SLee <i>SL</i>		JJankovich <i>JK</i>						
DATE	02/16/99		02/18/99						

CORD COPY

Mr. Reed Timko
 Grinnell Fire Protection Systems Company
 835 Sharon Drive
 Westlake, OH 44145

February 23, 1999

Dear Mr. Timko:

Based on the information and test data submitted in your application dated July 20, 1998, with enclosures thereto, we conclude that the Lo-Pro Series 612I and 912I smoke detectors are acceptable for licensing purposes in accordance with the conditions of the enclosed registration certificate (NR-0776-D-10¹²E).

As you requested that MF Series smoke detector registration certificate be transferred to inactive status by the fact these devices are no longer manufactured and distributed by Grinnell Fire Protection Systems Company and Grinnell Fire Protection Systems Company does not have any intention to produce them in the future. New registration number is NR-0-776-D-801-E. Copies of the certificates have been forwarded to the appropriate reviewer for licensing action.

Please be advised that you must manufacture and distribute the product in accordance with the statements and representations contained in your application, with enclosures thereto, and the information set out in your registration certificate. As a general rule, you must request and obtain an amendment to the certificate before you make changes or modifications to the information submitted to obtain the certificate.

Please read over the registration certificate in its entirety and notify us immediately of any errors or omissions.

You are obligated to notify us promptly in writing should you decide to no longer manufacture or offer service support for the product.

Please be aware that, as a holder of an NRC registration, you may be subject to the NRC's licensing and inspection fees in accordance with 10 CFR Part 170, and annual fees in accordance with 10 CFR Part 171. If you have any questions concerning the fee requirements, please contact the License Fee and Debt Collection Branch at (301) 415-7544.

If you have any questions, please contact me at (301) 415-5787 or Mr. John Jankovich at (301) 415-7904.

Sincerely,
/s/
 Seung J. Lee, Mechanical Engineer
 Materials Safety Branch
 Division of Industrial and
 Medical Nuclear Safety
 Office of Nuclear Material Safety
 and Safeguards

Enclosure: As stated
 cc w/encl: SKimberley, LFDCB

Distribution:

MSB r/f IMNS r/f SSD-98-81 NE01 *JL* SSD File # NR-0776-D-10¹²E

DOCUMENT NAME: C:\SJL\NR776101.CMP

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	MSB	E	MSB					
NAME	SLee <i>SL</i>		JJankovich <i>JJ</i>					
DATE	02/16/99		02/18/99 <i>JL</i>					