

ENERGY NORTHWEST

P.O. Box 968 ■ Richland, Washington 99352-0968

January 13, 2000
GO2-00-010

Docket No. 50-397

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Gentlemen:

Subject: **WNP-2, OPERATING LICENSE NPF-21
INSERVICE INSPECTION SUMMARY REPORT
R-14 MAINTENANCE AND REFUELING OUTAGE**

The WNP-2 Inservice Inspection Summary Report for the R-14 Maintenance and Refueling Outage is attached. This report is submitted in accordance with Section XI of the American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code Article IWA-6240. Pursuant to ASME Code Section XI, Article IWA-6230, the NIS-1 Owner's Data Report for inservice inspection and NIS-2 Owner's Reports for repairs and replacements are included.

Should you have any questions or require additional information pertaining to this report, please contact PJ Inserra at (509) 377-4147.

Respectfully,



RL Webring
Vice President, Operations Support/PIO
Mail Drop PE08

Attachments

cc: EW Merschoff - NRC-RIV
JS Cushing - NRC-NRR
TC Poindexter - Winston & Strawn

NRC Sr. Resident Inspector - 927N
DL Williams - BPA/1399

A047 1/1