

February 11, 2000
G-9000-JIM-00-008

Document Control Desk
United States Nuclear Regulatory Commission
Washington, D.C. 20555



- Reference: a) Boeing Letter G-1151-RSO-92-365 dated August 31, 1992; R. S. Orr to the NRC Operations Center
- b) NRC Letter Docket No. 99901227 dated August 12, 1992; L. J. Norrholm to R. S. Orr; Subject: Response to 10 CFR 21 Inquiry

Dear Sir or Madam:

In accordance with the reference correspondence and 10 CFR 21, Boeing is sending the NRC the attached error notice(s) received from our former software suppliers. Because of unknown current addresses, the following former customers were not notified:

Reactor Controls, Inc.
Echo Energy Consultants, Inc.
Nuclear Applications and Systems Analysis Company (Japan)
Nuclear Power Services

Error notices have been sent to our other former customers.

Very truly yours,

A handwritten signature in black ink that reads "John Maughan".

John I. Maughan
Nuclear Administrator
Phone: (425) 865-4785
FAX: (425) 865-2957
Mail Code: 7A-43
e-mail: john.i.maughan@boeing.com

Enclosure(s): GTSTRUDL Program Report Form 2000.02

IE20



February 2, 2000

Attention: Nuclear Administrator
Boeing Shared Services Group
P.O.Box 3707, MC 7A-33
Seattle, Washington 98124-2207

RE: GT STRUDL

Dear Sir or Madam:

Enclosed please find copies of GTSTRUDL PROGRAM REPORT FORM 2000.02, and a GTSTRUDL QA CUSTOMER ACKNOWLEDGEMENT FORM. Please sign and return the GTSTRUDL QA CUSTOMER ACKNOWLEDGEMENT FORM to acknowledge receipt of the GTSTRUDL Program Report.

Thank you for reviewing the Program Report and for returning the Acknowledgement Form.

Best regards,
CASE Center

David C. Key
Configuration Control Manager

Enclosures

GTSTRUDL Program Report Form

GPRF No.: 2000.02

DATE: 2/2/2000

FROM: Computer-Aided Structural Engineering Center
Georgia Institute of Technology
Atlanta, Georgia 30332-0355

SEVERITY LEVEL:

- URGENT Problem results in incorrect answers which may not be apparent or job aborts and cannot be recovered within the session or job.
- SERIOUS Problem results in incorrect answers which are obvious or problem prevents completion of a particular user's task.
- MINOR Problem can be worked around or problem poses high frustration factor.
- INFORMATIVE Documentation error, program usage tip, user inconveniences.

Date Problem Confirmed 2/1/2000

Date Notification Sent 2/2/2000

Computers All

Operating System All

Version All versions prior to and including Version 99.01

Kenneth M. Will
Signature
R & D Division

Director, ASD
Title

Kenneth M. Will
Typed or Printed Name

2/2/2000
Date of Signature

David C. Key
Signature
Professional Services Division

Configuration Control Manager
Title

David C. Key
Typed or Printed Name

2/2/2000
Date of Signature

GTSTRUDL Program Report Form
(Continued)

GPRF No.: 2000.02

DATE: 2/2/2000

DESCRIPTION:

This GPRF is a correction to the Description of GPRF 99.24.

In GPRF 99.24, it is stated that "The incorrect output will show a THETA angle of 45 degrees or 1.5707 radians."

The correction statement is "The incorrect output will show a THETA angle of 45 degrees or 0.785398 radians."