

BWRVIP

BWR Vessel & Internals Project

2000-079

March 24, 2000

Document Control Desk
U. S. Nuclear Regulatory Commission
11555 Rockville Pike
Rockville, MD 20852

Attention: C. E. Carpenter

Subject: Project 704 - Transmittal of "BWR Vessel and Internals Project, Standby Liquid Control Line Repair Design Criteria (BWRVIP-53NP)," EPRI Report TR-108716NP, March 2000.

Reference: Letter from C. Terry to C. E. Carpenter, June 16, 1998: Transmittal of "BWR Vessel and Internals Project, Standby Liquid Control Line Repair Design Criteria (BWRVIP-53)," EPRI Report TR-108716, July 1998.

Enclosed are two (2) copies of the subject report. This is the non-proprietary version of the document submitted to the NRC by the letter referenced above.

If you have any questions on this subject please call Steve Lewis of Entergy, BWRVIP Assessment Committee Chairman, at (601) 368-5444.

Sincerely,



Carl Terry
Niagara Mohawk Power Company
Chairman, BWR Vessel and Internals Project

Enclosure

DOSB