

March 31, 2000

Mr. Oliver D. Kingsley  
President, Nuclear Generation Group  
Commonwealth Edison Company  
ATTN: Regulatory Services  
Executive Towers West III  
1400 Opus Place, Suite 500  
Downers Grove, IL 60515

SUBJECT: CORRECTION TO NRC INSPECTION REPORT 50-454/2000003(DRS);  
50-455/2000003(DRS)

Dear Mr. Kingsley:

On March 28, 2000, the NRC issued inspection report, 50-454/2000003(DRS);  
50-455/2000003(DRS), documenting an NRC inspection of engineering, 10 CFR 50.59  
evaluations and screenings, and corrective action activities at the Byron Plant. After the report  
was issued, an error was noted in the Section entitled, "Items Opened, Closed, and Discussed."  
We have corrected this Section and have attached the corrected copy to this letter. Please  
replace this Section of the report with the attached "Items Opened, Closed, and Discussed"  
Section.

We apologize for any inconvenience or problems this error may have caused you. We will  
gladly discuss any questions you have concerning this error or the inspection.

Sincerely,

/RA/

Ronald N. Gardner, Chief  
Electrical Engineering Branch  
Division of Reactor Safety

Docket Nos. 50-454; 50-455  
License Nos. NPF-37; NPF-66

Enclosure: Correction to Inspection Report 50-454/2000003(DRS);  
50-455/2000003(DRS)

See Attached Distribution

DOCUMENT NAME: G:\DRS\BYR033\00DRS.WPD

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RIII	C	RIII	E	RIII	N	
NAME	HWalker <i>RWJ</i>		MJordan <i>MJ</i>		RGardner <i>RW</i>		
DATE	04/1/2000		04/1/2000		04/1/2000		

OFFICIAL RECORD COPY

Template RGN-002

O. Kingsley

-2-

cc w/encl: D. Helwig, Senior Vice President, Nuclear Services  
C. Crane, Senior Vice President, Nuclear Operations  
H. Stanley, Vice President, Nuclear Operations  
R. Krich, Vice President, Regulatory Services  
DCD - Licensing  
W. Levis, Site Vice President  
R. Lopriore, Station Manager  
K. Moser, Acting Regulatory Assurance Manager  
M. Aguilar, Assistant Attorney General  
State Liaison Officer  
State Liaison Officer, State of Wisconsin  
Chairman, Illinois Commerce Commission

Distribution:

WES (E-Mail)  
GFD (Project Mgr.) (E-Mail)  
J. Caldwell, RIII w/encl  
B. Clayton, RIII w/encl  
SRI Byron w/encl  
DRP w/encl  
DRS w/encl  
RIII PRR w/encl  
PUBLIC IE-01 w/encl  
Docket File w/encl  
GREENS  
RIII\_IRTS (E-Mail)  
DOCDESK (E-Mail)

## ITEMS OPENED, CLOSED, AND DISCUSSED

### Opened

50-454/455/2000003-01      NCV      Design changes for one modification were not correctly translated into procedures and instructions.

### Closed

50-454/455/1998004-01      URI      Untimely testing of breaker interlock logic circuit contacts, in response to NRC Generic Letter 96-01.

50-454/455/1998004-02      VIO      A field change request was not subjected to design control measures commensurate with those applied to the original design and as-built drawings and seismic calculations did not match the plant design.

50-454/455/1998004-03 (a)      VIO      Untimely corrective actions to correct the degraded condition of bolts and anchors for the auxiliary feed-water battery rack.

50-454/455/1998004-03(c)      VIO      Inadequate corrective actions to ensure that a field installed modification had been properly completed and tested before placing the modification in service.

50-454/455/1998004-04      VIO      Failure to establish an effective process for independent inspection and verification of modification activities.

50-454/455/1998004-05      URI      Incomplete action plan to assess the impact of cable impedance changes on marginally acceptable circuits.

50-454/455/1998004-06      URI      Lack of studies or evaluations to address appropriate methods for pressure control during reactor shutdown and cool-down without the pressurizer heaters.

50-454/455/1999001-01      IFI      Error in voltage calculations for safety related breaker coils.

50-454/455/2000003-01      NCV      Design changes for one modification were not correctly translated into procedures and instructions. Licensee personnel initiated PIF B2000-00139 to address corrective actions for this violation.

### Discussed

No items identified in previous NRC inspections were discussed without closing.