

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

April 3, 2000

Director of Nuclear Reactor Regulation
United States Nuclear Regulatory Commission
Washington, DC 20555-0001

Serial No.: 00-182
NLOS/MM
Docket No.: 50-338
License No.: NPF-4


Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY
NORTH ANNA POWER STATION UNIT 1
STEAM GENERATOR TUBE INSPECTION REPORT

Planned inservice inspection of the North Anna Unit 1 "B" steam generator was completed during the spring 2000 refueling outage. In accordance with North Anna Power Station Technical Specifications, Surveillance Requirement 4.4.5.5.a, this letter provides notification that no steam generator tubes were plugged during the outage.

No new commitments are intended by this letter. If you have any questions, concerning these results, please contact us.

Very truly yours,



J. H. McCarthy, Manager
Nuclear Licensing and Operations Support

cc: U. S. Nuclear Regulatory Commission
Region II
Atlanta Federal Center
61 Forsyth St., SW, Suite 23 T85
Atlanta, GA 30303-3415

Mr. M. J. Morgan
NRC Senior Resident Inspector
North Anna Power Station

A001