



Florida Power & Light Company, 6351 S. Ocean Drive, Jensen Beach, FL 34957

May 10, 2000

L-2000-117
10 CFR 50.36
10 CFR 50.4

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Re: St. Lucie Unit 2
Docket No. 50-389
Special Report
Steam Generator Tube Plugging Report

This letter is being sent pursuant to St. Lucie Unit 2 Technical Specification 4.4.5.5.a. The following number of tubes were plugged during the Unit 2 refueling outage SL2-12.

Steam Generator 2A - 26
Steam Generator 2B - 28

Cumulative tubes plugged during this outage and previous outages:

Steam Generator 2A - 345
Steam Generator 2B - 307

Should you have any questions on this information, please contact us.

Very truly yours,

A handwritten signature in black ink, appearing to read 'Rajiv S. Kundalkar', is written over a light blue horizontal line.

Rajiv S. Kundalkar
Vice President
St. Lucie Plant

RSK/spt

cc: Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, St. Lucie Plant

A001