



**UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064**

June 27, 2000

Randal K. Edington, Vice President - Operations
River Bend Station
Entergy Operations, Inc.
P.O. Box 220
St. Francisville, Louisiana 70775

SUBJECT: CORRECTION TO NRC INSPECTION REPORT NO. 50-458/99-12

Dear Mr. Edington:

NRC Inspection Report 50-458/99-12 was issued on October 19, 1999, with errors in the closed item listing in the attachment to the inspection report. Specifically, a number of violations which had previously been cited were listed as noncited violations. The closed violations were properly described in the main body of the inspection report. Since this error could lead to confusion, we are issuing corrected pages. Please replace pages 1 and 2 of the inspection report attachment with the revised pages enclosed with this letter. We regret any inconvenience this may have caused.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/NRC/ADAMS/index.html> (the Public Electronic Reading Room).

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

/RA/

William D. Johnson, Chief
Project Branch B
Division of Reactor Projects

Docket No.: 50-458
License No.: NPF-47

Enclosure:
As stated

Entergy Operations, Inc.

-2-

cc w/enclosure:
Executive Vice President and
Chief Operating Officer
Entergy Operations, Inc.
P.O. Box 31995
Jackson, Mississippi 39286-1995

Vice President
Operations Support
Entergy Operations, Inc.
P.O. Box 31995
Jackson, Mississippi 39286-1995

General Manager
Plant Operations
River Bend Station
Entergy Operations, Inc.
P.O. Box 220
St. Francisville, Louisiana 70775

Director - Nuclear Safety
River Bend Station
Entergy Operations, Inc.
P.O. Box 220
St. Francisville, Louisiana 70775

Wise, Carter, Child & Caraway
P.O. Box 651
Jackson, Mississippi 39205

Mark J. Wetterhahn, Esq.
Winston & Strawn
1401 L Street, N.W.
Washington, DC 20005-3502

Manager - Licensing
River Bend Station
Entergy Operations, Inc.
P.O. Box 220
St. Francisville, Louisiana 70775

The Honorable Richard P. Ieyoub
Attorney General
Department of Justice
State of Louisiana
P.O. Box 94005
Baton Rouge, Louisiana 70804-9005

Entergy Operations, Inc.

-3-

H. Anne Plettinger
3456 Villa Rose Drive
Baton Rouge, Louisiana 70806

President
West Feliciana Parish Police Jury
P.O. Box 1921
St. Francisville, Louisiana 70775

Ronald Wascom, Administrator
and State Liaison Officer
Department of Environmental Quality
P.O. Box 82135
Baton Rouge, Louisiana 70884-2135

Electronic distribution from ADAMS by RIV:

Regional Administrator (**EWM**)

DRP Director (**KEB**)

DRS Director (**ATH**)

Senior Resident Inspector (**TWP**)

Branch Chief, DRP/B (**WDJ**)

Senior Project Engineer, DRP/B (**RAK1**)

Branch Chief, DRP/TSS (**LAY**)

RITS Coordinator (**NBH**)

Only inspection reports to the following:

D. Lange (**DJL**)

NRR Event Tracking System (**IPAS**)

RBS Site Secretary (**PJS**)

Wayne Scott (**WES**)

R:_RB\RB912RP-COR.wpd

RIV:SRI:DRP/B	C:DRP/B			
TWPruett	WDJohnson			
<i>T - WDJohnson</i>	<i>/RA/</i>			
6/27/00	6/27/00			

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

ATTACHMENT

PARTIAL LIST OF PERSONS CONTACTED

Licensee

R. Edington, Vice President-Operations
T. Hildebrandt, Manager, Maintenance
J. Holmes, Manager, Radiation Protection and Chemistry
R. King, Director, Nuclear Safety and Regulatory Affairs
D. Mims, General Manager, Plant Operations
J. McGhee, Manager, Operations
D. Pace, Director, Engineering
M. Bakarich, Manager, Emergency Preparedness

INSPECTION PROCEDURES USED

IP 37551: Onsite Engineering
IP 61726: Surveillance Observations
IP 62707: Maintenance Observations
IP 71707: Plant Operations
IP 71750: Plant Support
IP 92901: Followup-Operations
IP 92901: Followup-Maintenance
IP 92903: Followup-Engineering
IP 92904: Followup-Plant Support

ITEMS OPENED AND CLOSED

Open and Closed

50-458/9912-01	NCV	Failure of operating personnel to be aware of plant indications
50-458/9912-02	NCV	Failure to translate information into specifications and procedures
50-458/9912-03	NCV	Failure to test service water time retention relays
50-458/9912-04	NCV	Failure to perform adequate technical evaluations

Closed

50-458/99-02	LER	Discovery of unanalyzed air filters on containment unit coolers
50-458/9820-01	VIO	Failure to ensure containers were not contaminated prior to release

50-458/9816-04	VIO	Failure to consider increased dose consequences to be an unreviewed safety question
50-458/9812-01	VIO	Failure to operate plant breakers in accordance with clearance order requirements
50-458/9812-02	VIO	Failure to maintain sirens operable
50-458/9805-01	VIO	Failure to control changes to environmental design criteria
50-458/9804-02	VIO	Failure of containment isolation damper
50-458/9803-01	VIO	Failure to maintain records of radiation protection program reviews
50-458/9803-02	VIO	Failure to follow radiation protection procedures
50-458/9719-01	VIO	Failure to follow procedures addressing electrical separation criteria
50-458/9719-03	VIO	Failure to maintain post accident sampling system operable
50-458/9719-05	VIO	Inadequate corrective actions to address air instrument sensing lines
50-458/9717-04	VIO	Failure to comply with Technical Specification Action after airlock surveillance failed
50-458/9714-02	IFI	Long-term plans to address RHR heat exchanger biofouling
50-458/9714-04	VIO	Failure to maintain a locked high radiation area barricaded and posted
50-458/9714-05	VIO	Failure to maintain a locked high radiation area door locked