

Pace, Paul L.

From: Pace, Paul L.  
Sent: Monday, March 27, 2000 7:58 AM  
To: 'GAB@NRC.GOV'; 'PEF@NRC.GOV'  
Subject: New Ice Screw information

AI/Paul

As we were preparing the information for the upcoming enforcement conference, we interviewed the original lab analyst who told us that in 1995 there were never any cracks found in "new screws" (Set B). He prepared the attached to show that the original report screw crack in Fig. 7 labelled "Set B" was changed in the second report to be correctly labelled as Set A since it was one of the screws from the melt tank in the plant. The difference in the figures was due to the preparation of the metal to show the graining visible in the 2nd report.

Because this information was missed in our LAB report reconciliation PER in 1998, I have issued a corrective action document (PER) to correct the existing QA records.

Since the citation for the conference is largely about not dealing with cracks in the warehouse screws and there actually were none found at that time, I didn't want to surprise you with this information at the conference.


Paul Pace, Licensing & Industry Affairs

ENCLOSURE


615 365 1924 P. 02/03

TUN WBN SITE U.P.

MAR-27-2000 09:10



REPORT 1 - Figure 7 Set "B"



REPORT 2 - Figure 7 Set "A"



REPORT 1 - Figure 7 Set "B"



REPORT 2 - Figure 7 Set "A"



OVERLAP