

August 24, 2000

MEMORANDUM TO: Donald C. Cook Nuclear Plant Manual Chapter 0350 Panel
FROM: John A. Grobe, Director, DRS */RA/*
SUBJECT: MINUTES OF INTERNAL MEETING OF THE DONALD C. COOK
NUCLEAR PLANT MANUAL CHAPTER 0350 PANEL

The Donald C. Cook Nuclear Plant Manual Chapter 0350 Panel charter was announced on April 17, 1998, and most recently revised on March 3, 2000. These internal meetings are used to discuss significant technical and performance issues, NRC regulatory approach, and inspection resources and priorities. Attached for your information are the minutes from the internal meeting of the Inspection Manual Chapter 0350 Restart Panel held on August 10, 2000.

Docket Nos. 50-315; 50-316

Attachment: As stated

cc w/att: M. Satorius, NRR
J. Zwolinski, NRR
S. Singh Bajwa, NRR
C. Craig, NRR
J. Stang, NRR
J. Thompson, NRR
J. Grobe, RIII
A. Vogel, RIII
M. Holmberg, RIII
B. Bartlett, RIII
D. Passehl, RIII
K. Coyne, RIII
J. Maynen, RIII
Docket Files

DOCUMENT NAME: G:\COOK\0350INTERNALMEETINGS\dcc081000.SUM

To receive a copy of this document, indicate in the box: "C" = Copy w/o attach/encl "E" = Copy w/attach/encl "N" = No copy

OFFICE	RIII:DRP	HQ:NRR	RIII:DRP	
NAME	AVegel/co	CCraig	JGrobe	
DATE	08/21/00	08/6/00	08/24/00	

OFFICIAL RECORD COPY

MEETING MINUTES: Internal MC 0350 Restart Panel Meeting
on the D. C. Cook Nuclear Plant

DATE: August 10, 2000

TIME: 9:00 a.m. (Central)

ATTENDEES:

S. Bajwa

K. Coyne

C. Craig

G. Grant

J. Maynen

D. Passehl

J. Stang

A. Vogel

Discussion Topics:

1. *Plant Status and Inspector Insights*

Unit 1

Plant personnel are in the process of working through restart issues. The next two milestones are completion of the "A" Train electrical outage, followed by starting the chill of the ice condenser. Following completion of these two milestones, the licensee has scheduled a second electrical outage on both trains, followed by open vessel testing and core reload.

Unit 2

The unit is at full power. The licensee is currently working on completing the root cause investigation into the degradation of the unit's essential service water pumps. The licensee is also investigating an issue raised by the resident inspectors regarding the operation of the safeguards ventilation units under certain postulated accident conditions.

2. *Discussion of Licensing Plan*

Mr. Stang summarized the Unit 1 restart submittals requiring NRC action. The Inspection Manual Chapter 0350 Panel held extensive discussion on the Unit 1 containment transient mass distribution analysis and related structural issues. NRR took action to discuss with the licensee the schedule for completion of the TMD analysis. The panel will further discuss the need/approach to review the licensee's final analysis prior to restart. Region III took action to add the containment issues to the agenda for the September 27, 2000, Inspection Manual Chapter 0350 public meeting.

3. *Discuss Restart Action Matrix for Unit 1*

Mr. Vogel led a discussion on development of a restart action matrix for Unit 1. The major steps in the development include identifying and prioritizing issues. The goal is to have the restart action matrix ready for issuance within the next few weeks.

4. *Discuss/Update Milestones and Commitments*

The Inspection Manual Chapter 0350 Panel discussed important upcoming meetings and deadlines.