

September 5, 2000

MEMORANDUM TO: Donald C. Cook Nuclear Plant Manual Chapter 0350 Panel
FROM: John A. Grobe, Director, DRS */RA/*
SUBJECT: MINUTES OF INTERNAL MEETING OF THE DONALD C. COOK
NUCLEAR PLANT MANUAL CHAPTER 0350 PANEL

The Donald C. Cook Nuclear Plant Manual Chapter 0350 Panel charter was announced on April 17, 1998, and most recently revised on August 4, 2000. These internal meetings are used to discuss significant technical and performance issues, NRC regulatory approach, and inspection resources and priorities. Attached for your information are the minutes from the internal meeting of the Inspection Manual Chapter 0350 Restart Panel held on August 23, 2000.

Docket Nos. 50-315; 50-316

Attachment: As stated

cc w/att: M. Satorius, NRR
J. Zwolinski, NRR
S. Singh Bajwa, NRR
C. Craig, NRR
J. Stang, NRR
J. Thompson, NRR
J. Grobe, RIII
A. Vogel, RIII
M. Holmberg, RIII
B. Bartlett, RIII
D. Passehl, RIII
K. Coyne, RIII
J. Maynen, RIII
Docket Files

DOCUMENT NAME: G:\COOK\0350INTERNALMEETINGS\dcc082300.SUM

To receive a copy of this document, indicate in the box: "C" = Copy w/o attach/encl "E" = Copy w/attach/encl "N" = No copy

OFFICE	RIII:DRP	HQ:NRR	RIII:DRP	
NAME	AVegel/co	CCraig	JGrobe	
DATE	08/29/00	08/29/00	09/05/00	

OFFICIAL RECORD COPY

MEETING MINUTES: Internal MC 0350 Restart Panel Meeting
on the D. C. Cook Nuclear Plant

DATE: August 23, 2000

TIME: 9:30 a.m. (Central)

ATTENDEES:

S. Bajwa
K. Coyne
C. Craig
J. Grobe
J. Jacobson

J. Maynen
B. Bartlett
J. Stang
A. Vogel
J. Thompson
J. Lamb

Discussion Topics:

1. *Plant Status and Inspector Insights*

Unit 1

Plant personnel are in the process of working through restart issues. The next two milestones are completion of the "A" Train electrical outage, followed by completing the chill of the ice condenser. Following completion of these two milestones, the licensee has scheduled a second electrical outage on both trains, followed by open vessel testing and core reload.

Unit 2

The unit is at full power. The licensee is currently working on completing the root cause investigation into the degradation of the unit's essential service water pumps. The licensee initiated a 1 hour stand-down to focus attention on recent issues involving human performance errors.

2. *Discussion of Inspection Plan*

Mr. Bartlett summarized the inspection plan for the next routine resident inspection period. The Inspection Manual Chapter 0350 Panel held extensive discussion on the utilization of new baseline inspection procedures. The panel decided that some time should be allocated for resident followup of MC 0350 issues, in addition to the additional time being planned for review of Unit 2 operational performance, and Unit 1 modification inspections.

3. *Discuss Restart Action Matrix for Unit 1*

Mr. Vogel led a discussion on development of the Restart Action Matrix (RAM) for Unit 1. The Inspection Manual Chapter 0350 Panel held extensive discussion of a draft RAM including identifying and prioritizing issues. The panel decided that the RAM should be divided into five major areas including Confirmatory Action Letter verification, High Priority Restart Issues, Licensee Event Reports, Licensing issues, and Guidelines

for Restart Approval. Another Internal Inspection Manual Chapter 0350 Panel meeting will be scheduled for the near future to further evaluate these issues which will be documented in the RAM.

4. *Discuss/Update Milestones and Commitments*

The Inspection Manual Chapter 0350 Panel discussed important upcoming meetings and deadlines.