



## THIS IS A 10CFR PART 21 NOTIFICATION

November 6, 2000

US Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Subject: 10CFR21 Notification Westronics Model CSVC

This letter is a notification of a defect associated with Westronics CSVC videographic recorders built under the Westronics 10CFR50 Appendix B Program.

On or about November 3, 2000, Westronics determined that Westronics Series CSVC "Smartview" Nuclear Safety Related videographic recorders, if utilized to measure thermocouple inputs, require hardware modifications to ensure accurate measurement. The hardware modification requires installation of capacitors associated with the Dallas 1620 Temperature Compensation Chips. Instruments which would require the modification were shipped between July 16, 1998 and July 7, 2000.

The following is the list of Nuclear Safety Related recorders which could potentially require modification:

<u>Recorder Serial #</u>	<u>Ship Date</u>	<u>Customer</u>	<u>Shipped To</u>	<u>Purchase Order</u>
CSVC2416	08/07/98	Entergy	Riverbend	RB980360
CSVC2417	08/07/98	Entergy	Riverbend	RB980360
CSVC2418	08/07/98	Entergy	Riverbend	RB980360
CSVC2419	08/07/98	Entergy	Riverbend	RB980360
CSVC2420	08/07/98	Entergy	Riverbend	RB980360
CSVC2421	08/07/98	Entergy	Riverbend	RB980360
CSVC2422	08/07/98	Entergy	Riverbend	RB980360
CSVC2423	08/07/98	Entergy	Riverbend	RB980360
CSVC2424	08/07/98	Entergy	Riverbend	RB980360

JE19

<u>Recorder Serial #</u>	<u>Ship Date</u>	<u>Customer</u>	<u>Shipped To</u>	<u>Purchase Order</u>
CSVC2425	08/07/98	Entergy	Riverbend	RB980360
CSVC2426	08/07/98	Entergy	Riverbend	RB980360
CSVC2427	08/07/98	Entergy	Riverbend	RB980360
CSVC2428	08/07/98	Entergy	Riverbend	RB980360
CSVC2429	08/07/98	Entergy	Riverbend	RB980360
CSVC2483	08/26/98	CP&L	Shearon Harris	9C2498DA
CSVC2484	08/26/98	CP&L	Shearon Harris	9C2498DA
CSVC2648	06/08/99	CP&L	Brunswick	1MF1492AF
CSVC2649	06/08/99	CP&L	Brunswick	1MF1492AF
CSVC2650	06/08/99	CP&L	Brunswick	1MF1492AF
CSVC2651	06/08/99	CP&L	Brunswick	1MF1492AF
CSVC2652	06/08/99	CP&L	Brunswick	1MF1492AF
CSVC2653	06/08/99	CP&L	Brunswick	1MF1492AF
CSVC2655	06/08/99	CP&L	Brunswick	1MF1492AF
CSVC2654	06/08/99	CP&L	Brunswick	1MF1492AF
CSVC2772	11/17/99	CP&L	Brunswick	1008882
CSVC2773	11/17/99	CP&L	Brunswick	1008882
CSVC2774	11/17/99	CP&L	Brunswick	1008882
CSVC2775	11/17/99	CP&L	Brunswick	1008882
CSVC2776	11/17/99	CP&L	Brunswick	1008882
CSVC2777	11/17/99	CP&L	Brunswick	1008882
CSVC2944	04/06/00	CP&L	Brunswick	1028953

Westronics Corrective Action includes installation of the capacitors noted above. Affected Customers will be notified in accordance with the requirements of 10CFR21. Westronics Contacts are the undersigned, Larry Zett, V.P. Production and Tech. Support, or Tony Pellegrini, Service Manager.

Sincerely,

  
Robert T. Agee

Quality Assurance Manager