John E. Sauter Radiation Safety Officer Honeywell Aerospace 717 North Bendix Drive South Bend, IN 46544

SUBJECT: RADIOLOGICAL CLOSE-OUT SURVEY REPORT 040-04930/2000001(DNMS)

Dear Mr. Sauter:

This refers to the inspection and radiological survey performed by NRC Inspectors on October 30, 2000, at the former Allied Signal Aerospace facility, located at 400 South Beiger Street, Mishawaka, Indiana. This inspection was conducted in response to your August 24, 2000, request to terminate NRC License No. STB-00286, and to release for unrestricted use your facilities located at 400 S. Beiger Street, Mishawaka, IN and at 29297 U.S. Highway 33 North, Elkhart, IN.

Based on our survey findings, and our review of your *Radiation Survey to Confirm Absence of Licensed Radioactive Material And Contamination* (attached to your August 24, 2000 Termination), no residual radiological contamination from past licensed activities was identified in these buildings. Therefore, we have determined that the two buildings meet NRC criteria for unrestricted release, as specified in 10 CFR Part 20, Subpart E, *"Criteria for License Termination."* The NRC has no further regulatory interest in these buildings unless additional contamination is found that indicates a threat to public health and safety. We are proceeding with a license amendment removing the subject buildings, which will be sent to you separately.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be available **electronically** for public inspection in the NRC Public Document Room <u>or</u> from the *Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from* the NRC Web site at <u>http://www.nrc.gov/NRC/ADAMS/index.html</u> (the Public Electronic Reading Room).

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

/RA/

Bruce L. Jorgensen, Chief Decommissioning Branch

Docket No. 040-04930 License No.STB-00286

cc: J. Ruyack, Indiana Department of Public Health

DOCUMENT NAME: C:\Allied Aerospace final clos~.wpd

To receive a copy of this document, indicate in the box: "C" = Copy without enclosure "E" = Copy with enclosure "N" = No copy

OFFICE	RIII	RIII		
NAME	McCann:js	Jorgensen		
DATE	11/07/00	11/07/00		

OFFICIAL RECORD COPY

J. Sauter

Distribution: Docket File PUBLIC IE-07 J. L. Caldwell, RIII C. D. Pederson, RIII RIII Enf. Coordinator

MATERIALS DECOMMISSIONING INSPECTION FIELD NOTES FOR FACILITIES NEEDING SIGNIFICANT DECOMMISSIONING EFFORT

Region:		III		
Inspection Report N	0.:	040-04	4930/2000002(DNMS)	
License No.:		STB-0	0286	
Docket No.:		040-04	4930	
Licensee (Name & Address):		Allied Signal Aerospace Guidance & Control Systems Mishawaka, Indiana 46544		
Licensee Contact:		John E	E. Sauter, Radiation Safety Officer	
Telephone No.:		(816)	987-3378	
Last Amendment No.:		07		
Date of Amendments	: March	28, 199	97	
Date of Last Inspect	ion:	Januar	y 19, 1999	
Date of This Inspection:		October 30, 2000		
Date of Next Inspection:		Not applicable (license to be terminated)		
Type of Inspection:	(X) Announce(X) Routine() Initial Deco		 () Unannounced (X) Special () Reinspection of Decomm. 	

Level of Inspection: (X) Normal () Reduced () Extended

Brief Description of Inspection Activities: This was a confirmatory radiological close out survey conducted in accordance with Ips 87104 and 83890. This survey was conducted in response to the licensee's August 24, 2000, request to terminate their NRC license. Based on the licensee's attached *Radiation Survey to Confirm Absence of Licensed Radioactive Material And Contamination* (Final Status Survey), NRC staff determined that a Confirmatory Survey at the licensee's former manufacturing facility located at 400 S. Beiger Street, Mishawaka was warranted.

Summary of Findings and Action:

- (\mathbf{X}) No violations cited, clear NRC Form 591 or regional letter issued
- () Violation(s), clear NRC Form 591 issued
- () Violation(s), regional letter issued
- () Follow up on previous violations

Inspectors	Mike McCann, M.S., Senior Decommissioning Inspector NRC Region III, Decommissioning Branch		
	William G. Snell, M.S., Senior Decommissioning Inspector NRC Region III, Decommissioning Branch		

NA

Accompanied By:

Approved by Branch Chief:

Bruce L	. Jorgensen, Chief, /RA/
Decom	nissioning Branch

Date:

1. <u>SUMMARY OF DECOMMISSIONING STATUS</u>

001	MART OF DECOMMISSIONING STATUS	
А.	Licensee ceased operational program.	(X) Y () N
В.	Required decommissioning financial assurance mechanisms	
	in place.	(X Y () N
C.	Decommissioning Plan (DP) required.	() Y (X) N
D.	Licensee final survey required.	() Y (x) N
E.	NRC confirmatory survey required.	(X) Y () N
F.	NRC closeout inspection required.	(X) Y () N
G.	Licensee doing decommissioning planning and preparation	
	before dismantlement.	() Y (X) N
H.	Licensee actively remediating site.	() Y (x) N
I.	Licensee completed site remediation.	(X) Y () N

Description of Facility Status: The licensee's license authorized two locations of use, i.e., 400 South Beiger Street, Mishawaka, In and 29297 U.S. Highway 33 North, Elkhart, IN. The Mishawaka location was used for machining of magnesium-thorium components used in the fabrication of missile drones for the Air Force. The Elkhart facility was used only for storage of finished missiles, no fabrication or machining occurred at this location. The licensee's letter of August 24, 2000, had attached: 1. a NRC Form 314 *Certificate of Disposition of Materials*, 2. a final status survey *Honeywell Guidance and control System, Materials License STB-286*, *Radiation Survey to Confirm Absence of Licensed Radioactive Material and Contamination*, and records of waste disposal.

2. **INSPECTION OF KEY DECOMMISSIONING ACTIVITIES**

THIS AREA NOT RELEVANT TO CLOSE OUT SURVEY, AND WAS NOT EVALUATED DURING THIS INSPECTION. DETAILS DELETED*

A. LICENSEE ACTIVITIES INSPECTED BEFORE DISMANTLEMENT

THIS AREA NOT RELEVANT TO CLOSE OUT SURVEY, AND WAS NOT EVALUATED DURING THIS INSPECTION. DETAILS DELETED*

B. LICENSEE ACTIVITIES INSPECTED DURING DECONTAMINATION, DISMANTLEMENT, AND SITE REMEDIATION

C. LICENSEE ACTIVITIES INSPECTED AFTER COMPLETION OF SITE REMEDIATION

- Licensee has submitted NRC Form 314 for disposition of licensed material in accordance with 10 CFR 30.36, 40.42, and 70.38.
 (X) Y () N
- 2. Licensee's final survey program is acceptable (see Appendix B for inspection items for final surveys). (X) Y () N
- 3. NRC confirmatory survey performed. (X) Y () N
- 4. Site maintenance activities (if any, for restricted use) conform to license conditions and NRC-approved plans and are in place and functional. (X) Y () N
- 5. Other licensee activities: () Y () N

<u>Basis for Findings</u>: Review of licensee's final status survey and inspector observations

3. INSPECTION OF STANDARD HEALTH AND SAFETY AREAS FROM THE OPERATIONAL INSPECTION PROGRAM

THIS AREA NOT RELEVANT TO CLOSE OUT SURVEY, AND WAS NOT EVALUATED DURING THIS INSPECTION. DETAILS DELETED*

B. FACILITIES

THIS AREA NOT RELEVANT TO CLOSE OUT SURVEY, AND WAS NOT EVALUATED DURING THIS INSPECTION. DETAILS DELETED*

C. EQUIPMENT AND INSTRUMENTATION

- 1. Survey instruments are applicable to contaminants of interest. (X) Y() N
- 2. Use of survey instruments appropriate for site. (x(Y () N

<u>Basis for Findings</u>: Review of licensee's final status survey and inspector observations.

D. MATERIALS

- 1. Radioactive materials licensed during operations have been removed offsite; residual quantities conform to license conditions. (X Y () N
- 2. Security and control of licensed materials, including contaminated areas, is being maintained. () Y () N

Basis for Findings:All material removed from site. Review of licensee's
final status survey, and inspector observations.

E. **TRAINING**

THIS AREA NOT RELEVANT TO CLOSE OUT SURVEY, AND WAS NOT EVALUATED DURING THIS INSPECTION. DETAILS DELETED*

F. AREA RADIATION SURVEYS AND CONTAMINATION CONTROL

THIS AREA NOT RELEVANT TO CLOSE OUT SURVEY, AND WAS NOT EVALUATED DURING THIS INSPECTION. DETAILS DELETED*

G. **RADIATION PROTECTION**

THIS AREA NOT RELEVANT TO CLOSE OUT SURVEY, AND WAS NOT EVALUATED DURING THIS INSPECTION. DETAILS DELETED*

H. RADIOACTIVE WASTE MANAGEMENT / EFFLUENTS / ENVIRONMENTAL MONITORING

THIS AREA NOT RELEVANT TO CLOSE OUT SURVEY, AND WAS NOT EVALUATED DURING THIS INSPECTION. DETAILS DELETED*

I. RECORD KEEPING FOR DECOMMISSIONING

THIS AREA NOT RELEVANT TO CLOSE OUT SURVEY, AND WAS NOT EVALUATED DURING THIS INSPECTION. DETAILS DELETED*

J. TRANSPORTATION

THIS AREA NOT RELEVANT TO CLOSE OUT SURVEY, AND WAS NOT EVALUATED DURING THIS INSPECTION. DETAILS DELETED*

K. **POSTING AND LABELING**

THIS AREA NOT RELEVANT TO CLOSE OUT SURVEY, AND WAS NOT EVALUATED DURING THIS INSPECTION. DETAILS DELETED*

L. OCCUPATIONAL HEALTH AND SAFETY

THIS AREA NOT RELEVANT TO CLOSE OUT SURVEY, AND WAS NOT EVALUATED DURING THIS INSPECTION. DETAILS DELETED*

4. VIOLATIONS, NON-CITED VIOLATIONS, FOLLOW UP ITEMS, AND OTHER ISSUES

Briefly state (1) the requirements and (2) how and when the licensee violated the requirement. For non-cited violations, indicate why the violation was not cited. Briefly describe follow up items and other issues.

a. A complete version of these field notes are attached NRC IP87104, Appendix A.