

December 6, 2000

Mr. Peter S. Hastings
Duke Cogema Stone & Webster
P.O. Box 31847
Charlotte, NC 28231-1847

SUBJECT: RESIDENT INSPECTOR OFFICE SPACE REQUIREMENTS

Dear Mr. Hastings:

In your letter of August 28, 2000, you provided a proposed conceptual arrangement for Nuclear Regulatory Commission inspector offices in the Mixed Oxide Fuel Fabrication Facility Administrative Building. You asked us to review the proposed arrangement and provide our concurrence.

NRC considers the amount of space adequate, but requires a modified arrangement. Since the resident inspectors will have a secretary/receptionist, the main entrance to the NRC residents' office area needs to be at the secretary's desk. The NRC residents' offices should be on one side of the secretarial area with the conference room on the other side of the secretarial area. This would provide needed privacy for the residents and visiting inspectors. The modified layout may require adjustment of room sizes.

If you have any further questions, please contact me at (301) 415-6522.

Sincerely,

/RA/

Andrew Persinko, Project Manager
Enrichment Section
Special Projects Branch
Division of Fuel Cycle Safety
and Safeguards, NMSS

Docket: 70-3098

cc: Mr. James Johnson, DOE
Mr. Henry Potter, SC Dept of Health &
Environmental Control
Mr. John T. Conway, Chairman, DNFSB

Mr. Peter S. Hastings
Duke Cogema Stone & Webster
P.O. Box 31847
Charlotte, NC 28231-1847

SUBJECT: RESIDENT INSPECTOR OFFICE SPACE REQUIREMENTS

Dear Mr. Hastings:

In your letter of August 28, 2000, you provided a proposed conceptual arrangement for Nuclear Regulatory Commission inspector offices in the Mixed Oxide Fuel Fabrication Facility Administrative Building. You asked us to review the proposed arrangement and provide our concurrence.

NRC considers the amount of space adequate, but requires a modified arrangement. Since the resident inspectors will have a secretary/receptionist, the main entrance to the NRC residents' office area needs to be at the secretary's desk. The NRC residents' offices should be on one side of the secretarial area with the conference room on the other side of the secretarial area. This would provide needed privacy for the residents and visiting inspectors. The modified layout may require adjustment of room sizes.

If you have any further questions, please contact me at (301) 415-6522.

Sincerely,

/RA/

Andrew Persinko, Project Manager
Enrichment Section
Special Projects Branch
Division of Fuel Cycle Safety
and Safeguards, NMSS

Docket: 70-3098

cc: Mr. James Johnson, DOE
Mr. Henry Potter, SC Dept of Health &
Environmental Control
Mr. John T. Conway, Chairman, DNFSB

DISTRIBUTION:

Docket 70-3098 ADAMS PUBLIC SPB r/f FCSS r/f
ELeeds EMcAlpine, RII D Ayres, RII

ADAMS Accession#: ML003774678

DOCUMENT NAME: G:\SPB\tcj\moxinspectspace.wpd *SEE PREVIOUS CONCURRENCE

OFC	SPB		SPB	E	SPB		SPB	
NAME	TJohnson:dr*		DHoadley*		APersinko*		MGalloway	
DATE	12/1/00		12/4/00		12/4/00		12/6/00	

C-COVER

E-COVER & ENCLOSURE
OFFICIAL RECORD COPY

N-NO COPY