

Docket No. 50-247

Mr. Peter Zarakas  
 Vice President - Engineering  
 Consolidated Edison Company  
 of New York, Inc.  
 4 Irving Place  
 New York, New York 10003

Dear Mr. Zarakas:

The Order for Modification of License dated August 29, 1980, contained incorrect references. We have accordingly revised the Order. In view of this revision, the date for which a hearing may be requested is also accordingly revised.

Sincerely,

Original Signed by  
RA Purple for

Darrell G. Eisenhut, Director  
 Division of Licensing

Enclosure:  
 Revised Order

cc: See next page

8101 100629

SCIMP

OFFICE ▶	DL:ORB1	DL:ORB1	DL:ORB1	DL:ORB1	DL:ORB2	DL:ORB2
SURNAME ▶	LNOTshan:jb	CSParrish	SAVanga	SAVanga	SAVanga	DGEisenhut
DATE ▶	09/16/80	09/16/80	09/16/80	09/16/80	09/16/80	09/19/80



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

September 19, 1980

Docket No. 50-247

Mr. Peter Zarakas  
Vice President - Engineering  
Consolidated Edison Company  
of New York, Inc.  
4 Irving Place  
New York, New York 10003

Dear Mr. Zarakas:

The Order for Modification of License dated August 29, 1980, contained incorrect references. We have accordingly revised the Order. In view of this revision, the date for which a hearing may be requested is also accordingly revised.

Sincerely,

  
Darrell G. Eisenhut, Director  
Division of Licensing

Enclosure:  
Revised Order

cc: See next page

Mr. Peter Zarakas

Consolidated Edison Company of New York, Inc. - 2 - September 19, 1980

cc: White Plains Public Library  
100 Martine Avenue  
White Plains, New York 10601

Joseph D. Block, Esquire  
Executive Vice President  
Administrative  
Consolidated Edison Company  
of New York, Inc.  
4 Irving Place  
New York, New York 10003

Richard Remshaw  
Nuclear Licensing Engineer  
Consolidated Edison Company  
of New York, Inc.  
4 Irving Place  
New York, New York 10003

Ms. Eilyn Weiss  
Sheldon, Harmon and Weiss  
1725 I Street, N.W., Suite 506  
Washington, D. C. 20006

Dr. Lawrence R. Quarles  
Apartment 51  
Kendal at Longwood  
Kennett Square, Pennsylvania 19348

Theodore A. Rebelowski  
Resident Inspector  
U. S. Nuclear Regulatory Commission  
P. O. Box 38  
Buchanan, New York 10511

John D. O'Toole  
Assistant Vice President  
Consolidated Edison Company  
of New York, Inc.  
4 Irving Place  
New York, New York 10003

Carl R. D'Alvia, Esquire  
Attorney for the Village of  
Buchanan, New York  
395 South Riverside Avenue  
Croton-on-Hudson, New York 10520

Jeffrey C. Cohen, Esquire  
New York State Energy Office  
Swan Street Building  
CORE 1 - Second Floor  
Empire State Plaza  
Albany, New York 12223

Director, Technical Development  
Programs  
State of New York Energy Office  
Agency Building 2  
Empire State Plaza  
Albany, New York 12223

Director, Technical Assessment Division  
Office of Radiation Programs (AW-459)  
U. S. Environmental Protection Agency  
Crystal Mall #2  
Arlington, Virginia 20460

U. S. Environmental Protection Agency  
Region II Office  
ATTN: EIS COORDINATOR  
26 Federal Plaza  
New York, New York 10007

Joyce P. Davis, Esquire  
Law Department  
Consolidated Edison Company  
of New York, Inc.  
4 Irving Place  
New York, New York 10003

Mr. Peter Zarakas  
Consolidated Edison Company of New York, Inc. - 3 - September 19, 1980

cc: Mr. William A. Monti, Manager  
Nuclear Power Generation Dept.  
Consolidated Edison Company  
of New York, Inc.  
Broadway and Bleakley Avenues  
Buchanan, New York 10511

Mr. Michael F. Shatkouski  
Plant Manager  
Consolidated Edison Company  
of New York, Inc.  
Broadway and Bleakley Avenues  
Buchanan, New York 10511

Mr. John M. Makepeace  
Director of Technical Engineering  
Consolidated Edison Company  
of New York, Inc.  
Broadway and Bleakley Avenues  
Buchanan, New York 10511

UNITED STATES OF AMERICA  
NUCLEAR REGULATORY COMMISSION

In the Matter of	)	
CONSOLIDATED EDISON COMPANY OF	)	Docket No. 50-247
NEW YORK, INC.	)	
(Indian Point, Unit No. 2)	)	

REVISED ORDER FOR MODIFICATION OF LICENSE

I.

Consolidated Edison Company of New York, Inc. (the licensee) is the holder of Facility Operating License No. DPR-23, which authorizes the operation of Indian Point, Unit No. 2 at steady state reactor power levels not in excess of 2758 megawatts thermal (rated power). The facility consists of a pressurized water reactor located at the licensee's site in Westchester County, New York.

II.

On November 4, 1977, the Union of Concerned Scientists (UCS) filed with the Commission a "Petition for Emergency and Remedial Relief." The petition sought action in two areas: fire protection for electrical cables, and environmental qualification of electrical components. By Memorandum and Order dated April 13, 1978 (7 NRC 400), the Commission denied certain aspects of the petition and, with respect to other aspects, ordered the NRC staff to take several related actions. UCS filed a Petition for Reconsideration on May 2, 1978. By Memorandum and Order, dated May 23, 1980, the Commission reaffirmed its April 13, 1978 decision

8101100634

regarding the possible shutdown of operating reactors. However, the Commission's May 23, 1980 decision directed licensees and the NRC staff to undertake certain actions.

With respect to environmental qualification of safety-related electrical equipment, the Commission determined that the provisions of the two staff documents - the Division of Operating Reactors "Guidelines for Evaluating Environmental Qualification of Class 1E Electrical Equipment in Operating Reactors" (DOR Guidelines) and NUREG-0588, "Interim Staff Position on Environmental Qualification of Safety-Related Electrical Equipment," December 1979 "form the requirements which licensees and applicants must meet in order to satisfy those aspects of 10 CFR Part 50, Appendix A General Design Criterion (GDC-4), which relate to environmental qualification of safety-related electrical equipment." The Commission directed, for replacement parts in operating plants, "unless there are sound reasons to the contrary, the 1974 standard in NUREG-0588 will apply." The Commission also directed the staff to complete its review of the information sought from licensees by Bulletin 79-01B<sup>1</sup> and to complete its review of environmental qualification of safety-related electrical equipment in all operating plants, including the publication of Safety Evaluation Reports, by February 1, 1981. The Commission

---

<sup>1</sup> Bulletin 79-01B was not sent to licensees for plants under review as part of the staff's Systematic Evaluation Program. The information sought by Bulletin 79-01B was requested from these licensees by a series of letters and meetings during the months of February and March, 1980.

imposed a deadline that, "by no later than June 30, 1982 all safety-related electrical equipment in all operating plants shall be qualified to the DOR Guidelines or NUREG-0588." The Commission requested the staff to, "keep the Commission and the public apprised of any further findings of incomplete environmental qualification of safety-related electrical equipment, along with corrective actions taken or planned," and requested the staff to provide bi-monthly progress reports to the Commission.

The Commission further directed the staff to add certain documentation requirements to each license after the specific requirements were approved by the Commission. The Commission also pointed out that the various deadlines imposed in its Order, "do not excuse a licensee from the obligation to modify or replace inadequate equipment promptly."

### III.

The information developed during this proceeding emphasizes the importance of adequate documentation, the prompt completion of the review of environmental qualification of safety-related electrical equipment, and the prompt completion of any plant modification needed to assure conformance with the DOR Guidelines or NUREG-0588. A significant aspect of this review is the timely submittal of environmental qualification information by the operating plant licensees to enable the staff to complete its review in accordance with the Commission's Order. The staff has a program presently underway to reevaluate, using the DOR Guidelines and NUREG-0588, the qualifications of safety-related electrical equipment exposed

to environments that may exist following postulated accidents. These accidents are Loss of Coolant Accident and Main Steam Line Break inside containment, and High Energy Line Breaks inside and outside containment.

In this connection the licensee was requested by our letter of March 5, 1980, as modified by our letter of March 20, 1980 to provide information on emergency procedures and safety related systems. The licensee was requested to define and provide the basis for the hostile environment, inside and outside containment. This hostile environment would then be used, by the licensee, in the determination of unqualified equipment. A complete package, including justification for methods used, was requested.

Clarification was provided by supplemental information, briefings, and in some cases, meetings with the licensee. Timely completion of the staff's review of environmental qualification of electrical equipment and timely completion of needed modifications by the licensee is required to provide continuing reasonable assurance of public health and safety. Such completion is dependent on the prompt receipt of a complete response by the licensee to the staff's requests for information. However, the licensee's response, to date, is incomplete.

Therefore, I have concluded that the public health, safety, and interest require that a firm schedule for the timely submission of all the

information previously requested by the staff should be established by Order effective immediately.

IV.

Accordingly, pursuant to the Atomic Energy Act of 1954, as amended, and the Commission's regulations in 10 CFR Parts 2 and 50, IT IS ORDERED THAT EFFECTIVE IMMEDIATELY Facility Operating License No. DPR-26 is hereby amended to add the following provisions:


"Information which fully and completely responds to the staff's request as specified in our letter of March 5, 1980, as modified by our letter of March 20, 1980, shall be submitted to the Director, Division of Licensing, by the licensee not later than November 1, 1980."

An earlier response is encouraged to facilitate staff review and issuance of the safety evaluation report. The licensee or any person whose interest may be affected by this Order may request a hearing within 20 days of the date of publication of this Revised Order in the Federal Register. Any request for a hearing will not stay the effective date of this Order. Any request for a hearing shall be addressed to the Director, Office of Nuclear Reactor Regulation, U. S. Nuclear Regulatory Commission, Washington, D. C. 20555. A copy of the request should also be sent to the Executive Legal Director, U. S. Nuclear Regulatory Commission, Washington, D. C. 20555, and to Brent L. Brandenburg, Consolidated Edison Company of New York, Inc., 4 Irving Place, New York, New York 10019, attorney for the licensee.

If a hearing is held concerning this Order, the issue to be considered at the hearing shall be whether the license should be modified to require submission of information as set forth in Section IV. of the Order.

Operating of the facility on terms consistent with this Order is not stayed by the pendency of any proceedings on the Order. This Order revises, in its entirety, the Order issued August 29, 1980, and published in the Federal Register September 11, 1980, (45 FR 60072).

FOR THE NUCLEAR REGULATORY COMMISSION

  
Darrell G. Eisenhut, Director  
Division of Licensing

Effective Date: September 19, 1980  
Bethesda, Maryland