



SINCLAIR RESEARCH, INC.
400 EAST SIBLEY BOULEVARD
HARVEY, ILLINOIS 60426

OFFICE OF THE VICE PRESIDENT

April 27, 1968

-04

Mr. Edmund J. Oparka
U. S. Atomic Energy Commission
Region III, Division of Compliance
799 Roosevelt Road
Glen Ellyn, Illinois 60426

Dear Sir:

In accordance with your letter of April 17, 1968,
we are returning herewith Forms AEC-591, INSPECTION
FINDINGS AND LICENSEE ACKNOWLEDGEMENT.

Yours very truly,

SINCLAIR RESEARCH, INC.


E. J. Martin

Enclosures

MAY 3 1968

A/54

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

E(1) IL 216

<p>1. LICENSEE</p> <p>Sinclair Research, Incorporated 400 East Sibley Boulevard Harvey, Illinois 60426</p>	<p>2. REGIONAL OFFICE</p> <p>U.S. ATOMIC ENERGY COMMISSION REGION III, DIVISION OF COMPLIANCE 350 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137</p>
<p>3. LICENSE NUMBER(S)</p> <p>12-00140-04</p>	<p>4. DATE OF INSPECTION</p> <p>April 4, 1968</p>

5. INSPECTION FINDINGS

- A. No item of noncompliance was found.
- B. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA.
10 CFR 20.203(b) or 34.42
- C. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA.
10 CFR 20.203(c) (1) or 34.42
- D. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA.
10 CFR 20.203(d)
- E. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL.
10 CFR 20.203(e)
- F. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL.
10 CFR 20.203(f) (1) or (f) (2)
- G. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)
- H. Form AEC-3 was not properly posted. 10 CFR 20.206(c)
- I. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)
- J. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)
- K. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained.
10 CFR 30.51, 40.61 or 70.51
- L. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)
- M. Records of inventories were not maintained. 10 CFR 34.26
- N. Utilization logs were not maintained. 10 CFR 34.27

Edmund J. Opatka
(AEC Compliance Inspector)

6. LICENSEE'S ACKNOWLEDGMENT

The AEC Compliance Inspector has explained and I understand the items of noncompliance listed above. The items of noncompliance will be corrected within the next 30 days.

April 27, 1968 (Date) *[Signature]* (Licensee Representative - Title or Position)

ORIGINAL: LICENSEE. COPIES: CO REGION CO HEADQUARTERS CO ENFORCEMENT

Mailed 5-6-68