**Dave Morey** Vice President Farley Project Southern Nuclear Operating Company P.O. Box 1295 Birmingham, Alabama 35201 Tel 205.992.5131

January 9, 2001 Docket Nos.: 50-348 50-364



U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D. C. 20555-0001

> Joseph M. Farley Nuclear Plant Monthly Operating Report

Ladies and Gentlemen:

Enclosed are the December 2000 Monthly Operating Reports for Joseph M. Farley Nuclear Plant Units 1 and 2, as required by Section 5.6.4 of the Technical Specifications.

If you have any questions, please advise.

Respectfully submitted,

Mory

Dave Morey

RWC:mor

Enclosures:

- 1. December Monthly Operating Report for Plant Farley Unit 1
- 2. December Monthly Operating Report for Plant Farley Unit 2

TED

Page 2 U. S. Nuclear Regulatory Commission

~

Ľ,

cc: Southern Nuclear Operating Company Mr. L. M. Stinson, General Manager

> U. S. Nuclear Regulatory Commission, Washington, D. C. Mr. L. M. Padovan, Licensing Project Manager – Farley

U. S. Nuclear Regulatory Commission, Region II Mr. L. A. Reyes, Regional Administrator Mr. T. P. Johnson, Senior Resident Inspector – Farley

<b>DOCKET NO.:</b>	50-348
UNIT NAME:	J. M. Farley - Unit 1
DATE:	January 5, 2001
COMPLETED BY:	W. L. Marlar
TELEPHONE:	(334) 814-4554

# **OPERATING STATUS**

4

1.	Reporting Period:	<b>DECEMBER 2000</b>
2.	Design Electrical Rating (Net MWe):	854
3.	Maximum Dependable Capacity (Net MWe):	828

		<u>This Month</u>	Year to Date	<b>Cumulative</b>
4.	Number Of Hours Reactor Was Critical:	744.0	6,812.3	164,437.7
5.	Hours Generator On-line:	744.0	6,775.9	162,231.2
6.	Unit Reserve Shutdown Hours:	0.0	0.0	0.0
7.	Net Electrical Energy Generated (MWH):	632,986.0	5,199,584.0	127,960,417.0

# CHALLENGES TO PRESSURIZER PORV OR PRESSURIZER SAFETY VALVES

Date	Tag No.	Event Description
		There were no challenges to Pressurizer PORV or Pressurizer Safety Valves.

# DOCKET NO.: 50-348 UNIT NAME: J. M. Farley - Unit 1 DATE: January 5, 2001 COMPLETED BY: W. L. Marlar TELEPHONE: (334) 814-4554

# REPORTING PERIOD: DECEMBER 2000

No.DateF: ForcedDurationReasonShutting DownCause/CorrectiveNo.DateS: Scheduled(Hours)(1)(2)Comment	
There were no unit shu during the month.	utdowns

(2) METHOD:

4 - Continuation 5 - Other (Explain)

2 - Manual Trip/Scram3 - Automatic Trip/Scram

1 - Manual

(1) REASON:

A - Equipment Failure (Explain)

- B Maintenance or Test
- C Refueling
- D Regulatory Restriction
- E Operator Training/License Examination
- F Administrative
- G Operational Error (Explain)
- H Other (Explain)

# CAUSE/CORRECTIVE ACTION/COMMENTS

# NARRATIVE REPORT

At 1800 on 001201 the unit was ramped down to approximately 75% power to repair a cooling tower header manifold valve. The unit was returned to 100% power at 0732 on 001202.

<b>DOCKET NO.:</b>	50-364
UNIT NAME:	J. M. Farley - Unit 2
DATE:	January 5, 2001
COMPLETED BY:	W. L. Marlar
TELEPHONE:	(334) 814-4554

# **OPERATING STATUS**

. .

1.	Reporting Period:	<b>DECEMBER 2000</b>
2.	Design Electrical Rating (Net MWe):	855
3.	Maximum Dependable Capacity (Net MWe):	838

		<u>This Month</u>	Year to Date	<u>Cumulative</u>
4.	Number Of Hours Reactor Was Critical:	744.0	8,750.7	148,509.5
5.	Hours Generator On-line:	744.0	8,736.2	146,624.0
6.	Unit Reserve Shutdown Hours:	0.0	0.0	0.0
7.	Net Electrical Energy Generated (MWH):	631,586.0	7,362,558.0	116,815,086.0

# CHALLENGES TO PRESSURIZER PORV OR PRESSURIZER SAFETY VALVES

Date	Tag No.	Event Description
		There were no challenges to Pressurizer PORV or Pressurizer Safety Valves.



# **UNIT SHUTDOWNS**

#### DOCKET NO.: 50-364 UNIT NAME: J. M. Farley - Unit 2 January 5, 2001 DATE: W. L. Marlar **COMPLETED BY: TELEPHONE:** (334) 814-4554

### **REPORTING PERIOD: DECEMBER 2000**

Method of Type Cause/Corrective Actions Shutting Down Duration Reason F: Forced Comments (2)No. (Hours) (1)Date S: Scheduled There were no unit shutdowns during the month. (2) METHOD: (1) REASON 1 - Manual A - Equipment Failure (Explain) 2 - Manual Trip/Scram B - Maintenance or Test 3 - Automatic Trip/Scram C - Refueling 4 - Continuation D - Regulatory Restriction 5 - Other (Explain)

E - Operator Training/License Examination

F - Administrative

G - Operational Error (Explain)

H - Other (Explain)

## **CAUSE/CORRECTIVE ACTION/COMMENTS**

#### NARRATIVE REPORT

At 0802 on 001201 the Unit was ramped down to approximately 80% to repair a cooling tower cell. The unit was returned to 100% power at 2027 on 001202.