

22 May 95 TZ8601 Work: CRD-V-14B

Boldface = cardreader computer records

1025 () relieves () to grind on CRD-V-14B,
() is the fire watch.

1028 NRC inspectors enter RB via door R105.

NRC inspectors walk by, and enter HPCS pump room.

Removed packing gland and retaining ring.

() leaves to get lubricant or solvent.

1034 () exits the RB via door R204.

1037 Stopped grinding, need pipe wrench. No further hot work on this valve is performed during this event.

1037 () enters the RB via door R204.

1040 () leaves to get pipe wrench from tool room just as () returns. () now acting as fire watch.

1042 () exits the RB via door R105.

() kneels at the base of CRD-P-1B to clean valve parts.

() walks to tool box to get punch to remove the bonnet.

() walks to phone 25' away (in room, but out of line of sight) to page () since pipe wrench isn't needed now. () is at phone for less than two minutes.

NRC inspectors (Proulx, Werner) arrive at work site, they do not see anyone in the area.

() returns and is questioned by inspectors, states he is the fire watch. Werner asks him if it is "legal" for him to have relieved () as fire watch. () tells him yes. Werner repeats the question twice.

() leaves to call to ensure taking fire watch from () was allowed (it was).

() returns and tells inspectors he can be the fire watch.

() gives this time as 1042.

Porter
7C

mm/7

NRC inspectors leave.

1046 NRC inspectors exit RB via door R105.

1048 [REDACTED] enters RB via door R105.

[REDACTED] returns

1055 [REDACTED] instructs [REDACTED] to remain in the area until 1110.
[REDACTED] and [REDACTED] leave for lunch.

[REDACTED] leaves the room.

1055 [REDACTED] and [REDACTED] leave the RB via door R105.

1112 [REDACTED] leaves the RB via door R105.

Botone
7C