Region I NMSS Licensee Event Report

Ditte of

60	License No. Seneral
μ ν	Docket No.
	MLER-RI 2001 - 00
ICENSEE: YATES	COMPANY
VENT DESCRIPTION LOSS OF LEAS	SED IONIZER MODEL P-2021 S/N 116470
VENT DATE	REPORT DATE 1-22-01
REPORTING REQUIREMENT () 10 CFR 20.2201 Theft or Loss () 10 CFR 20.2203 30 Day Repo () 10 CFR 30.50 Report () Other	ort () License Condition
REGION I RESPONSE	
() Immediate Site Inspection () Special Inspection () Telephone Inquiry () Preliminary Notification () Information Entered on the RI () Review at Next Routine Inspection () Report Referred to	Log
REPORT EVALUATION	
() Description of Event () Levels of RAM Involved () Cause of Event	(') Corrective Actions () Calculation Adequate () Letter to Licensee Requesting Additional Information
4. <u>SPECIAL INSTRUCTIONS OR C</u>	COMMENTS
Completed By:	Date
Reviewed By E Ullin	S Date 1/31/01
	PK6 H
G:\LAS\LERForm Revised 12/20/99	•

ML 010 310272 NMSS/RGN-006



RECEIVED REGION 1

YATES COMPANY 2001 JAN 22 PM 2: 47 CUSTOM PLASTIC EXTRUSIONS

January 15th 2001 US Nuclear Regulatory Commission 475 Allendale Road King Of Prussia, PA 19406-1415

Dear Sir or Madam,

NRD has advised me that I have to notify you in writing as to the loss of a leased Ionizer model No. P-2021, S/N 116470. Yates Co. is a Plastic Extrusion Co. We use these devices for cleaning our material hoppers. They are very effective at eliminating any static in the hoppers, which holds the material and makes cleaning difficult.

We believe that this particular device was never returned to the Supervisors office, left on the production floor swept up and thrown in the trash. It has been missing since October 2000. I' am having 3" x 5" plastic tags attached to our new Ionizers reminding our employees to return the devices after they are used.

> 。 一个工作的EDSO 主意 "你们的EDV"的专用。在各种的时间,是自由于"专用各种"等处于

Sincerely,

Ľarfy J. LaSota

Engineering Manager

cc: CAC File

