

LEAK TEST CERTIFICATE

Wipe Date 9/15/00

DESCRIPTION OF DEVICE/SOURCE

Model 500/C Ser 2073

	SOURCE 1	SOURCE 2
Material	<u>CS-137</u>	<u>AM-241/DE</u>
Source Ser	<u>28266Q</u>	<u>NJ02113</u>

RSO Name JOE FRANCIS

Telephone (304)340-4277

Do Not Write In This Space  
For HSI Use Only

REMOVABLE ACTIVITY

Be 0 Gam 0 Alpha 0 uCi 0 uCi

Humboldt Scientific

By DTL

Date 9/29/00

Instructions

- 1 Use wipe procedures as described in the device manual.
- 2 Enter all information under description.
- 3 Print or type return address in the space provided.
- 4 Wipe source (s) and put filter paper in the plastic bag.
- 5 Keep the middle copy and mail this form and bag to Humboldt.
- 6 Regulations require that sources with removable activity greater than 0.005 uCi be removed from service for repair and decontamination or disposal. Authorities must be notified.

5200174  
Return  
Address  
Label  
Please  
Type or  
Print  
Clearly

American Geotech, Inc.  
601 Ohio Avenue  
Charleston, West Virginia 25302

HUMBOLDT SCIENTIFIC INC. 5510 Pylon Drive, Raleigh, NC 27606, (919) 832-6509