

NYOO

[Handwritten signature]

LR:RH

OCT 12 1961

Eastman Kodak Company
Kodak Park Works
Rochester 4, New York

Attention: Mr. John Mulder, Administrative
Assistant to General Manager

Gentlemen:

Thank you for your letter of September 21, 1961, informing us that you have corrected those deficiencies in your AEC licensed program which we brought to your attention in our letter of September 13, 1961. These matters will be reviewed during the next inspection of your facilities.

Your cooperation with us is appreciated.

Very truly yours,

Richard E. Cunningham, Chief
Enforcement Branch
Division of Licensing
and Regulation

bcc: Compliance Division, HO)
Compliance Division, NYOO)w/cpy ltr 9/13/61
Public Document Room)

OCT 18 1961

LR:EB

LR:EB

RH:med

RECunningham

10/6/61

RECEIVED
ITEM # 45

B145

③

PLEASE ADDRESS REPLY TO:
FREDERICK J. WOODS

EASTMAN KODAK COMPANY

ROCHESTER 4 NEW YORK

TELEPHONE
AREA NUMBER 41000

SEPTEMBER 20, 1950

Mr. Elmer R. Priden, Assistant Director
Division of Licensure and Inspection
United States Atomic Energy Commission
Washington 25, D.C.

RE: 2410

Dear Sir:

Pursuant to the provisions of Section 161 of the "Atomic Energy Control Act of 1946," of the Atomic Energy Control Act of 1946, Title 10, Code of Federal Regulations, we have given notice that the violations described in your report of the AEC Inspector on April 15, 1950, regarding activities and materials under your license No. 2410, regarding activities and materials under your license No. 2410, have been corrected.

Deficiencies, with respect to which a deficiency under license No. 2410, are:

1. As of August 2, 1950, collection No. 1 of the license was amended to read "for material contained therein, the use of which is not permitted under the license." This amendment was approved by the Radiation Protection Committee, of the Atomic Energy Commission, Secretary."

2. The small-60 sealed sources are not being kept at a readily accessible surface at six-month intervals. The test which was performed on August 20, 1950.

3. A violation, Radioactive material, is not being kept in a readily accessible surface at six-month intervals. The test which was performed on August 20, 1950.

4. A violation, Radioactive material, is not being kept in a readily accessible surface at six-month intervals. The test which was performed on August 20, 1950.

5. A violation, Radioactive material, is not being kept in a readily accessible surface at six-month intervals. The test which was performed on August 20, 1950.

6) The storage well containing the 5 curie cobalt-60 source had been labeled as required by Section 20.203 (f)(1) and (1)(4).

With reference to license compliance:

7) The glove box containing radioactive material has been labeled as required by Section 20.203 (1)(4). This was done in the presence of the inspector on April 19, 1961.

Very truly yours,

J. A. Mander
J. A. Mander, Administrative
Assistant to General Manager
Rockwell Laboratories

JN:jb
RFS