



April 20, 2001

L-2001-105
10 CFR 50.36
10 CFR 50.4

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Re: St. Lucie Unit 1
Docket No. 50-335
Special Report
Steam Generator Tube Plugging Report

This letter is being sent pursuant to St. Lucie Unit 1 Technical Specification 4.4.5.5.a. The following number of tubes were plugged during the Unit 1 refueling outage SL1-17.

Steam Generator 1A - 0
Steam Generator 1B - 0

Cumulative tubes plugged during this outage and previous outages:

Steam Generator 1A - 11
Steam Generator 1B - 0

Please contact us should you have any questions regarding this information.

Very truly yours,

A handwritten signature in black ink, appearing to read 'Rajiv S. Kundalkar', is written over the typed name.

Rajiv S. Kundalkar
Vice President
St. Lucie Plant

RSK/spt

cc: Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, St. Lucie Plant

A001