

Region II
NMSS Licensee Event Report

License No.: General Licensee Docket No.: N/A Event No.: N/A

Licensee: Freedom Lincoln Mercury (static eliminator)

Event Type: Static eliminator found in a vacant residential area

Event Date: 04/30/01 Report Date: 04/30/01

1. REPORTING REQUIREMENT

- | | |
|--|---|
| <input checked="" type="checkbox"/> 10 CFR 20.2201 Theft or Loss | <input type="checkbox"/> 10 CFR 35.33 Misadministration |
| <input type="checkbox"/> 10 CFR 20.2203 30 Day Report | <input type="checkbox"/> License Condition _____ |
| <input type="checkbox"/> 10 CFR 30.50 Report | <input type="checkbox"/> Other _____ |

2. REPORT EVALUATION

- Description of Event Attached
- Type/Quantity of RAM Involved 10 mCi, Po-210
- Preliminary Occupational Dose () Greater than Limit () Less than Limit
- Preliminary Public Dose () Greater than Limit () Less than Limit
- Excessive Radiation Levels or Concentrations _____ X Part 20 Concentrations
- Unrestricted Area Contamination
- Cause of Event Sealed source was apparently stolen from the car dealership
- Corrective Actions Adequate _____
- Calculation Adequate
- Potential Severity Level III, II, I
- Other _____

3. REGION II RESPONSE

- Immediate Site Inspection
- Special Inspection Inspector/Date _____
- Telephone Inquiry Inspector/Date: Wade Loo/05/01/01
- Review at Next Routine Inspection
- Preliminary Notification Number PNO-II-01-015
- Daily Report, MR Number _____
- Others Informed: () NMSS () STP () EDO Staff (X) State () Region () Other _____
- Report Referred to _____

4. SPECIAL INSTRUCTIONS OR COMMENTS

Licensee is in the process of having the sealed source sent back to the manufacturer
(AEA Technology QSA, Inc, Burlington, MA). Will conduct a special inspection to
followup on the circumstances surrounding the stolen sealed source during the next
routine inspections scheduled in the Chesapeake, Virginia area.

Completed By: *Wade Loo* Date 5/1/01
Reviewed By: *ATB* Date 5/2/01