NUCLEAR POWER BUSINESS UNIT TRAINING JOB PERFORMANCE MEASURES

JPM P000.023COT Revision 0 DRAFT July 11, 2000 TOTAL REWRITE

RESPOND TO LOSS OF CONTAINMENT SUMP RECIRCULATION CAPABILITY

K/A REFERENCE: E11 EK1.2 (3.6/4.1) (NUREG-1122) E11 EK3.3 (3.8/3.8) E11 EA2.2 (3.4/4.2)
ALTERNATE PATH JPM YES X NO
ABILKIMILIAM TES A NO
PERFORMANCE CHECKLIST:
SATISFACTORY - Properly performed critical step(s) and/or in sequence (if applicable)
<u>UNSAT</u> ISFACTORY - Improperly performed critical step(s) and/or out of sequence (if applicable)
X Procedure adequately addresses task elements. Enter identifier here: ECA-1.1, Rev. 23
Other document adequately describes necessary task elements. Enter identifier here:
X Task elements described as attached.
DESIRED MODE OF EVALUATION: APPLICABLE EVALUATION SETTING:
SIMULATE/WALKTHROUGH X DISCUSSION PERFORM X IN-PLANT CONTROL ROOM X
VALIDATED TIME FOR COMPLETION: 15 MINUTES

POINT BEACH NUCLEAR PLANT EMERGENCY CONTINGENCY ACTION

LOSS OF CONTAINMENT SUMP RECIRCULATION

ECA-1.1 UNIT 1 SAFETY RELATED Revision 23 8/10/00 Page 12 of 35

T							
ST	EP	ACTION/EXPECTED	RESPONSE		RESPONSE	NOT	OBTAINED
ь				J		1101	OBININED

Check If SI Should Be Terminated:

a. Check reactor vessel level from a. Go to Step 25. table below - SATISFIED

RCPs RUNNING	REQUIRED REACTOR VESSEL LEVEL
1	wide range greater than [100 ft] 95 ft
0	narrow range greater than [30 ft] 27 ft

b. Check RCS subcooling based on core exit thermocouples - GREATER THAN [130°F] 85°F

- b. Establish minimum injection flow to remove decay heat:
 - 1) Determine minimum injection flow required for decay heat removal per FIGURE 1.
 - 2) Try to establish minimum required injection flow using charging flow.
 - 1HC-142
 - 3) IF minimum required injection flow can NOT be established using charging flow. THEN reduce SI flow to establish 225 gpm on desired SI pump.
 - o 1SI-866A for pump A o 1SI-866B for pump B
 - 4) IF 225 gpm SI pump flow can NOT be established. THEN establish 525 gpm on desired RHR pump.
 - o 1RH-624 for pump A o 1RH-625 for pump B
 - 5) Stop SI and RHR pumps not required to maintain minimum required injection flow.
 - 6) Go to <u>Step 25</u>.