

REVIEWER NOTE FOR NR-8122-D-801-E and NR-8122-D-102-E

FROM: Seung J. Lee /**RA**/ 03/20/01

The checklist was not used because the distributor had been out of service since Oct. Therefore, no safety evaluation of the device was performed as part of the conversion of the certificate to inactive status.

Working life was not added because no new safety evaluation was conducted.

Please see the KBM Enterprises, Inc. letter dated August 17, 2000, and conversation log with Jeff Knight of KBM dated March 19, 2001.