

From: William Bearden *RE*
To: Gary Claxton, Peter VanDoorn
Date: Thu, Apr 13, 2000 2:04 PM
Subject: Screws

Whatever this newest info really means we should note that the original report mentioned zinc in the cracks (cracked before plating process). That means that the screw (be it "A" or "B") was probably an unused screw that that fallen into the ice bed. Does that mean it should have still been treated as a new screw.

P/1