June 15, 2001

Mr. Oliver D. Kingsley, President Exelon Nuclear Exelon Generation Company, LLC Executive Towers West III 1400 Opus Place, Suite 500 Downers Grove, IL 60515

SUBJECT: CORRECTION LETTER (TAC NOS. MB0807, MB0580, MB0581, MB0582, AND MB0583)

Dear Mr. Kingsley:

By letter dated January 12, 2001, the staff issued Amendment 115 to the license for Byron Station, Unit 1, reflecting the transfer of ownership of Byron Station from Commonwealth Edison Company to Exelon Generation Company, LLC. Page 1 of the license contained a typographical error. The corrected page is attached.

By letter dated May 17, 2001, the staff issued Amendment 120 to the licenses for Byron, Station, Units 1 and 2, and Amendment 114 to the licenses for Braidwood Station, Units 1 and 2. The amendments revised technical specification (TS) page 3.3.1 to delete the "Power Range Neutron Flux High Negative Rate" trip function from Table 3.3.1-1. The revised TS page was incorrectly identified as page 3.3.1-14. The correct TS page number should be 3.3.1-13. The corrected pages are attached. They should replace the present TS page 3.3.1-13. TS page 3.3.1-14 should be retained in its current form.

We apologize for any inconvenience that these errors may have caused.

Sincerely,

/**RA**/

George F. Dick, Jr., Project Manager, Section 2 Project Directorate III Division of Licensing Project Management Office of Nuclear Reactor Regulation

Docket Nos. STN 50-454, STN 50-455, STN 50-456, and STN 50-457

Enclosure: As stated

cc w/encl: See next page

O. Kingsley Exelon Generation Company

CC:

Ms. C. Sue Hauser, Project Manager Westinghouse Electric Corporation Energy Systems Business Unit Post Office Box 355 Pittsburgh, Pennsylvania 15230

Joseph Gallo Gallo & Ross 1025 Connecticut Ave., NW, Suite 1014 Washington, DC 20036

Howard A. Learner Environmental Law and Policy Center of the Midwest 35 East Wacker Dr., Suite 1300 Chicago, Illinois 60601-2110

U.S. Nuclear Regulatory Commission Byron Resident Inspectors Office 4448 N. German Church Road Byron, Illinois 61010-9750

Regional Administrator, Region III U.S. Nuclear Regulatory Commission 801 Warrenville Road Lisle, Illinois 60532-4351

Ms. Lorraine Creek RR 1, Box 182 Manteno, Illinois 60950

Chairman, Ogle County Board Post Office Box 357 Oregon, Illinois 61061

Mrs. Phillip B. Johnson 1907 Stratford Lane Rockford, Illinois 61107

George L. Edgar Morgan, Lewis and Bockius 1800 M Street, NW Washington, DC 20036-5869 Byron/Braidwood Stations

Attorney General 500 S. Second Street Springfield, Illinois 62701

Illinois Department of Nuclear Safety Office of Nuclear Facility Safety 1035 Outer Park Drive Springfield, Illinois 62704

Exelon Generation Company, LLC Byron Station Manager 4450 N. German Church Road Byron, Illinois 61010-9794

Exelon Generation Company, LLC Site Vice President - Byron 4450 N. German Church Road Byron, Illinois 61010-9794

U.S. Nuclear Regulatory Commission Braidwood Resident Inspectors Office 35100 S. Rt. 53, Suite 79 Braceville, Illinois 60407

Mr. Ron Stephens Illinois Emergency Services and Disaster Agency 110 E. Adams Street Springfield, Illinois 62706

Chairman Will County Board of Supervisors Will County Board Courthouse Joliet, Illinois 60434

Exelon Generation Company, LLC Braidwood Station Manager 35100 S. Rt. 53, Suite 84 Braceville, Illinois 60407-9619

Byron/Braidwood Stations

Ms. Bridget Little Rorem Appleseed Coordinator 117 N. Linden Street Essex, Illinois 60935

Document Control Desk-Licensing Exelon Generation Company, LLC 1400 Opus Place, Suite 500 Downers Grove, Illinois 60515

Exelon Generation Company, LLC Site Vice President - Braidwood 35100 S. Rt. 53, Suite 84 Braceville, Illinois 60407-9619

Mr. William Bohlke Senior Vice President, Nuclear Services Exelon Generation Company, LLC 1400 Opus Place, Suite 900 Downers Grove, Illinois 60515

Mr. H. Gene Stanley Operations Vice President Mid-West Regional Operating Group Exelon Generation Company, LLC 1400 Opus Place, Suite 900 Downers Grove, Illinois 60515

Mr. Christopher Crane Senior Vice President Mid-West Regional Operating Group Exelon Generation Company, LLC 1400 Opus Place, Suite 900 Downers Grove, Illinois 60515

Mr. R. M. Krich Director - Licensing Mid-West Regional Operating Group Exelon Generation Company, LLC 1400 Opus Place, Suite 900 Downers Grove, Illinois 60515 Exelon Generation Company, LLC Regulatory Assurance Supervisor - Braidwood 35100 S. Rt. 53, Suite 84 Braceville, Illinois 60407-9619

Exelon Generation Company, LLC Regulatory Assurance Supervisor - Byron 4450 N. German Church Road Byron, Illinois 61010-9794

Mr. Robert Helfrich Senior Counsel, Nuclear Mid-West Regional Operating Group Exelon Generation Company, LLC 1400 Opus Place, Suite 900 Downers Grove, Illinois 60515

Mr. Jeffrey Benjamin Vice President - Licensing and Regulatory Affairs Exelon Generation Company, LLC 1400 Opus Place, Suite 900 Downers Grove, Illinois 60515

Mr. John Skolds Chief Operating Officer Exelon Generation Company, LLC 1400 Opus Place, Suite 900 Downers Grove, Illinois 60515

Mr. John Cotton Senior Vice President - Operations Support Exelon Generation Company, LLC 1400 Opus Place, Suite 900 Downers Grove, Illinois 60515 Mr. Oliver D. Kingsley, President June 15, 2001 Exelon Nuclear Exelon Generation Company, LLC Executive Towers West III 1400 Opus Place, Suite 500 Downers Grove, IL 60515

SUBJECT: CORRECTION LETTER (TAC NOS. MB0807, MB0580, MB0581, MB0582, AND MB0583)

Dear Mr. Kingsley:

By letter dated January 12, 2001, the staff issued Amendment 115 to the license for Byron Station, Unit 1, reflecting the transfer of ownership of Byron Station from Commonwealth Edison Company to Exelon Generation Company, LLC. Page 1 of the license contained a typographical error. The corrected page is attached.

By letter dated May 17, 2001, the staff issued Amendment 120 to the licenses for Byron, Station, Units 1 and 2, and Amendment 114 to the licenses for Braidwood Station, Units 1 and 2. The amendments revised technical specification (TS) page 3.3.1 to delete the "Power Range Neutron Flux High Negative Rate" trip function from Table 3.3.1-1. The revised TS page was incorrectly identified as page 3.3.1-14. The correct TS page number should be 3.3.1-13. The corrected pages are attached. They should replace the present TS page 3.3.1-13. TS page 3.3.1-14 should be retained in its current form.

We apologize for any inconvenience that these errors may have caused.

Sincerely,

/RA/

George F. Dick, Jr., Project Manager, Section 2 Project Directorate III Division of Licensing Project Management Office of Nuclear Reactor Regulation

Docket Nos. STN 50-454, STN 50-455,	Distribution:		
STN 50-456, and STN 50-457	PUBLIC	ASTONE, RIII	
	PDIII/2		
Enclosure: As stated	JZWOLINSKI/CCARPENTER		
	AMENDIOLA		
cc w/encl: See next page	CROSENBERG		
	GDICK		
	MCHAWLA		
	OGC		
	ACRS		

DOCUMENT NAME:C:\Program Files\Adobe\Acrobat 4.0\PDF Output\correction.letter.wpd ML011640542

OFFICE	PM:PDIII/2	LA:PDIII/2		PM:PDIII/2	SC:PDIII/2	
NAME	GDICK	CROSENBER	۲G	MCHAWLA	AMENDIOLA	
DATE	06/14/01	06/14/01		06/14/01	06/15/01	

OFFICIAL RECORD COPY