

June 19, 2001

Mr. Robert P. Powers, Senior Vice President
Indiana Michigan Power Company
Nuclear Generation Group
500 Circle Drive
Buchanan, MI 49107

SUBJECT: DONALD C. COOK NUCLEAR PLANT, UNIT 2 - CORRECTION TO
AMENDMENT NO. 234 (TAC NO. MB1082)

Dear Mr. Powers:

On June 11, 2001, the Commission issued Amendment No. 234 to Facility Operating License No. DPR-74 for the Donald C. Cook Nuclear Plant, Unit 2. The amendment changed License Page 9 paragraph (x) to extend surveillance intervals associated with the emergency diesel generator engines and station batteries that are currently required to be completed beginning June 27, 2001. The license amendment allows these requirements to be performed during the next refueling outage, but no later than December 31, 2001. This would preclude the need for a mid-cycle shutdown of the unit.

The amendment consisted of changes to the License in response to your application dated January 19, 2001, as supplemented April 20 and May 9, 2001. Errors were inadvertently made on License Page 9 paragraph (x). The changes to the license condition contained in the licensee's May 9, 2001, letter, were not fully incorporated into the original proposed license condition. The word "inspection" in the first line of the first paragraph was removed. The word "has" was changed to "have" and "its" was changed to "their" in the third line of the first paragraph. The word "of" was added after the word requirements in the second line of the first paragraph. The word "the" was added in front of the word "refueling" in the third line of the second paragraph. The corrections do not, in any way, change the intent of license condition, which is to allow extension for the above stated surveillances. A corrected copy of page 9 is enclosed.

If you have any questions concerning this matter, please call me at (301) 415-1345.

Sincerely,

/RA/

John F. Stang, Senior Project Manager, Section 1
Project Directorate III
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-316

Enclosure: Corrected License Page 9

cc w/encl: See next page

June 19, 2001

Mr. Robert P. Powers, Senior Vice President
Indiana Michigan Power Company
Nuclear Generation Group
500 Circle Drive
Buchanan, MI 49107

SUBJECT: DONALD C. COOK NUCLEAR PLANT, UNIT 2 - CORRECTION TO
AMENDMENT NO. 234 (TAC NO. MB1082)

Dear Mr. Powers:

On June 11, 2001, the Commission issued Amendment No. 234 to Facility Operating License No. DPR-74 for the Donald C. Cook Nuclear Plant, Unit 2. The amendment changed License Page 9 paragraph (x) to extend surveillance intervals associated with the emergency diesel generator engines and station batteries that are currently required to be completed beginning June 27, 2001. The license amendment allows these requirements to be performed during the next refueling outage, but no later than December 31, 2001. This would preclude the need for a mid-cycle shutdown of the unit.

The amendment consisted of changes to the License in response to your application dated January 19, 2001, as supplemented April 20 and May 9, 2001. Errors were inadvertently made on License Page 9 paragraph (x). The changes to the license condition contained in the licensee's May 9, 2001, letter, were not fully incorporated into the original proposed license condition. The word "inspection" in the first line of the first paragraph was removed. The word "has" was changed to "have" and "its" was changed to "their" in the third line of the first paragraph. The word "of" was added after the word requirements in the second line of the first paragraph. The word "the" was added in front of the word "refueling" in the third line of the second paragraph. The corrections do not, in any way, change the intent of license condition, which is to allow extension for the above stated surveillances. A corrected copy of page 9 is enclosed.

If you have any questions concerning this matter, please call me at (301) 415-1345.

Sincerely,

/RA/

John F. Stang, Senior Project Manager, Section 1
Project Directorate III
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-316

Enclosure: Corrected License Page 9

cc w/encl: See next page

DISTRIBUTION:

PUBLIC	GHill(2)	JStang	WBeckner
PD III-1 Reading	OGC	THarris	SSaba
CCraig	ACRS	AVegel, RIII	OChopra

ACCESSION NO. ML011650054

OFFICE	PD3-1/PM	PD3-1/LA	PD3-1/SC
NAME	JStang	THarris	CCraig
DATE	6/19/01	6/19/01	6/19/01

OFFICIAL RECORD COPY

(v) Secondary Water Chemistry Monitoring Program

The licensee shall implement a secondary water chemistry monitoring program to inhibit steam generator tube degradation. This program shall be described in the station chemistry manual and shall include:

1. Identification of a sampling schedule for the critical parameters and control points for these parameters;
2. Identification of the procedures used to measure the values of the critical parameters;
3. Identification of process sampling points;
4. Procedure for the recording and management of data;
5. Procedures defining corrective actions for off control point chemistry conditions; and
6. A procedure identifying (a) the authority responsible for the interpretation of the data, and (b) the sequence and timing of administrative events required to initiate corrective actions.

(w) The steam generator tube inspection surveillance maximum inspection interval of Technical Specification 4.4.5.3 is extended until the start of cycle 13, but no later than June 30, 2002.

(x) The emergency diesel generator engine Technical Specification surveillance requirements of 4.8.1.1.2.e.1 and 4.8.1.1.2.e.7 have been extended to allow their performance during refueling outage 13, but no later than December 31, 2001.

The station battery service testing Technical Specification surveillance requirements 4.8.2.3.2.d and 4.8.2.5.2.d have been extended to allow them to be performed during the refueling outage 13, but no later than December 31, 2001.

Donald C. Cook Nuclear Plant, Units 1 and 2

cc:

Regional Administrator, Region III
U.S. Nuclear Regulatory Commission
801 Warrenville Road
Lisle, IL 60532-4351

Attorney General
Department of Attorney General
525 West Ottawa Street
Lansing, MI 48913

Township Supervisor
Lake Township Hall
P.O. Box 818
Bridgman, MI 49106

U.S. Nuclear Regulatory Commission
Resident Inspector's Office
7700 Red Arrow Highway
Stevensville, MI 49127

David W. Jenkins, Esquire
Indiana Michigan Power Company
Nuclear Generation Group
One Cook Place
Bridgman, MI 49106

Mayor, City of Bridgman
P.O. Box 366
Bridgman, MI 49106

Special Assistant to the Governor
Room 1 - State Capitol
Lansing, MI 48909

Drinking Water and Radiological
Protection Division
Michigan Department of
Environmental Quality
3423 N. Martin Luther King Jr Blvd
P.O. Box 30630, CPH Mailroom
Lansing, MI 48909-8130

Ronald Gaston
Director, Regulatory Affairs
Indiana Michigan Power Company
Nuclear Generation Group
One Cook Place
Bridgman, MI 49106

David A. Lochbaum
Union of Concerned Scientists
1616 P Street NW, Suite 310
Washington, DC 20036-1495

A. Christopher Bakken, Site Vice President
Indiana Michigan Power Company
Nuclear Generation Group
One Cook Place
Bridgman, MI 49106

Michael W. Rencheck
Vice President, Nuclear Engineering
Indiana Michigan Power Company
Nuclear Generation Group
500 Circle Drive
Buchanan, MI 49107