



Entergy Nuclear Generation Co.
Pilgrim Station
600 Rocky Hill Road
Plymouth, MA 02360

William J. Riggs
Director, Nuclear Assessment

June 28, 2001
ENGCLtr. 2.01.065

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Docket No. 50-293
License No. DPR-35

Subject: Pilgrim Station's Completion of Generic Letter 87-02 (Supplement 1), "Verification of Seismic Adequacy of Mechanical and Electrical Equipment in Operating Plants, Unresolved Safety Issue (USI) A-46"


Dear Sir:

This letter serves to notify the NRC of the completion of Pilgrim Station's actions taken in response to Generic Letter 87-02, Supplement 1 (USI A-46).

During the 2001 refueling outage (RFO-13), the outage-dependant work necessary to resolve the remaining A-46 equipment outliers was completed. All outliers identified by the initial implementation of Generic Implementation Procedure Revision 2 (GIP-2) and from the change that re-defined the effective grade of buildings have been resolved.

This letter provides the project completion information to allow the NRC staff to supplement the NRC Safety Evaluation of Pilgrim Station's A-46 program implementation. We request the supplemental safety evaluation be issued at the earliest convenience.

Please feel free to contact Douglas Ellis, (508) 830-8160, if there are any questions regarding this subject.



W.J. Riggs

DWE/

cc: Mr. Steven Bloom, Project Manager
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Mail Stop: OWFN 14B2
1 White Flint North
11555 Rockville Pike
Rockville, MD 20852

U.S. Nuclear Regulatory Commission
Region 1
475 Allendale Road
King of Prussia, PA 10406

Pilgrim Senior Resident Inspector

A025