OCT 2 0 1977

Docket Nos. 50-269 50-270 and 50-287

> Duke Power Company ATTN: Mr. William O. Parker, Jr. Vice President - Steam Production Post Office Box 2178 422 South Church Street Charlotte, North Caroline 28242

Gentlemen:

By letter dated October 4, 1977, we transmitted to you Amendment Nos. 47, 47 and 44 for License Nos. DPR-38, DPR-47 and DPR-55 for the Ocenee Nuclear Station, Unit Nos. 1, 2 and 3.

Page 3.5-9 of the Technical Specifications transmitted with the amendments contained an error. Item d.(2) has been changed as indicated on enclosed page 3.5-9.

Sincerely.

A. Schwencer, Chief Operating Reactors Branch #1 Division of Operating Reactors

Enclosure: Corrected page to Amendment Nos. 47, 47 and 44

cc w/encl: See next page

			 	T	
OFFICE	DORORB#1	DOR:ORB#1	 		
SURNAME >	DNeighbors:16	Aschwencer	 		
DATE	10/19/77	10/ /77	 		

X UI S. GOVERNMENT PRINTING OFFICE: 1976 - 626-624

DISTRIBUTION **Dockets** Nrc PDR LOCAL PDR ORB#1 Reading **KRGoller JMcGouah** ASchwencer DNeighbbrs SMSheppard oeld OI&E(5)DEisenhut **B**Jones **TBAbernahthy** JRBuchanan ACRS(16)



UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

October 20, 1977

Docket Nos. 50-269 50-270 and 50-287

> Duke Power Company ATTN: Mr. William O. Parker, Jr. Vice President - Steam Production Post Office Box 2178 422 South Church Street Charlotte, North Carolina 28242

Gentlemen:

By letter dated October 4, 1977, we transmitted to you Amendment Nos. 47, 47 and 44 for License Nos. DPR-38, DPR-47 and DPR-55 for the Oconee Nuclear Station, Unit Nos. 1, 2 and 3.

Page 3.5-9 of the Technical Specifications transmitted with the amendments contained an error. Item d.(2) has been changed as indicated on enclosed page 3.5-9.

Sincerely,

21662

A. Schwencer, Chief Operating Reactors Branch #1 Division of Operating Reactors

Enclosure: Corrected page to Amendment Nos. 47, 47 and 44

cc w/encl: See next page

- 2 - October 20, 1977

Duke Power Company

· -----

·····

cc: Mr. William L. Porter Duke Power Company P. O. Box 2178 422 South Church Street Charlotte, North Carolina 28242

> J. Michael McGarry, III, Esquire DeBevoise & Liberman 700 Shoreham Building 806-15th Street, NW., Washington, D.C. 20005

Oconee Public Library 201 South Spring Street Walhalla, South Carolina 29691

pump operation. Also, excepting physics tests or exercising control rods, the ixial power shaping control roginsertion/ withdrawal limits are specified on figures 3.5.2-4A1, 3.5.2-4A2 and 3.5.2-4A3 (Unit 1) and on figures 3.5.2-4B1, 3.5.2-4B2, and 3.5.2.4B3 (Unit 2). If the control rod position limits are exceeded, corrective measures shall be taken immediately to achieve an acceptable control rod position. An acceptable control rod position shall then be attained within two hours. The minimum shutdown margin required by Specification 3.5.2.1 shall be maintained at all times.

- d. Except for physics tests, power shall not be increased above the power level cutoff as shown on Figures 3.5.2-1A1, 3.5.2-1A2, 3.5.2-1A3, (Unit 1), 3.5.2-1B1, 3.5.2-1B2, and 3.5.2-1B3 (Unit 2), and 3.5.2-1C1, 3.5.2-1C2, 3.5.2-1C3 (Unit 3), unless the following requirements are met.
 - (1) The xenon reactivity shall be within 10 percent of the value for operation at steady-state rated power.
 - (2) The xenon reactivity worth has passed its final maximum or minimum peak during its approach to its equilibrium value for operation at the power level cutoff.
- .5.2.6 Reactor power imbalance shall be monitored on a frequency not to exceed two hours during power operation above 40 percent rated power. Except for physics tests, imbalance shall be maintained within the envelope defined by Figures 3.5.2-3A1, 3.5.2-3A2, 3.5.2-3A3, 3.5.3-3B1, 3.5.2-3B2, 3.5.2-3B3, 3.5.2-3C1, 3.5.2-3C2, and 3.5.2-3C3. If the imbalance is not within the envelope defined by these figures, corrective measures shall be taken to achieve an acceptable imbalance. If an acceptable imbalance is not achieved within two hours, reactor power shall be reduced until imbalance limits are met.
- 5.2.7 The control rod drive patch panels shall be locked at all times with limited access to be authorized by the manager or his designated alternate.