

-ERRATA-

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF NUCLEAR REACTOR REGULATION
WASHINGTON, D.C. 20555-0001

August 8, 2001

NRC INFORMATION NOTICE 2001-12 (ERRATA): HYDROGEN FIRE AT NUCLEAR
POWER STATION

Addressees

All holders of operating licenses or construction permits for nuclear power reactors except those who have ceased operations and have certified that fuel has been permanently removed from the reactor vessel.

Discussion

Two editorial errors have been identified in NRC Information Notice 2001-12, "Hydrogen Fire at Nuclear Power Station" (ADAMS Accession No. ML010310258), issued on July 13, 2001. The errors occurred in the Related Generic Communications section on Page 2. The number for the information notice titled "Hydrogen Storage on the Roof of the Control Room" should read "IN 89-44," not "IN 88-44." The number for the information notice titled "Compressed Gas Cylinder Missile Hazard" should read "IN 91-37," not "IN 91-27."

If there are any questions about this matter, please contact the staff members listed below or the appropriate Office of Nuclear Reactor Regulation (NRR) project manager.

/RA John R. Tappert Acting for/
Ledyard B. Marsh, Chief
Operational Experience and
Non-Power Reactors Branch
Division of Regulatory Improvement Programs

Technical contacts: D. M. Frumkin, NRR
301-415-2280
E-mail: dmf@nrc.gov

M. H. Salley, NRR
301-415-2840
E-mail: mhs@nrc.gov

Attachment: List of Recently Issued NRC Information Notices

ML012110235

-ERRATA-

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF NUCLEAR REACTOR REGULATION
WASHINGTON, D.C. 20555-0001

August 8, 2001

NRC INFORMATION NOTICE 2001-12 (ERRATA): HYDROGEN FIRE AT NUCLEAR
POWER STATION

Addressees

All holders of operating licenses or construction permits for nuclear power reactors except those who have ceased operations and have certified that fuel has been permanently removed from the reactor vessel.

Discussion

Two editorial errors have been identified in NRC Information Notice 2001-12, "Hydrogen Fire at Nuclear Power Station" (ADAMS Accession No. ML010310258), issued on July 13, 2001. The errors occurred in the Related Generic Communications section on Page 2. The number for the information notice titled "Hydrogen Storage on the Roof of the Control Room" should read "IN 89-44," not "IN 88-44." The number for the information notice titled "Compressed Gas Cylinder Missile Hazard" should read "IN 91-37," not "IN 91-27."

If there are any questions about this matter please contact the staff members listed below or the appropriate office of Nuclear Reactor Regulation (NRR) project manager.

/RA John R. Tappert Acting for/
Ledyard B. Marsh, Chief
Operational Experience and
Non-Power Reactors Branch
Division of Regulatory Improvement Programs

Technical contacts: D. M. Frumkin, NRR
301-415-2280
E-mail: dmf@nrc.gov

M. H. Salley, NRR
301-415-2840
E-mail: mhs@nrc.gov

Attachment: List of Recently Issued NRC Information Notices

DISTRIBUTION
PUBLIC
IN File

OFFICIAL RECORD COPY

Publicly Available Non-Publicly Available Sensitive Non-Sensitive

OFFICE	REXB	SC:REXB	C:REXB
NAME	CPetrone*	JTappert*	LMarsh/JRT for
DATE	08/08/2001	08/08/2001	08/08/2001

ML012110235

LIST OF RECENTLY ISSUED
 NRC INFORMATION NOTICES

Information Notice No.	Subject	Date of Issuance	Issued to
2001-12	Hydrogen Fire at Nuclear Power Stations	7/13/01	All holders of operating licenses or construction permits for nuclear power reactors except those who have ceased operations and have certified that fuel has been permanently removed from the reactor vessel
2001-11	Thefts of Portable Gauges	07/13/01	All portable gauge licensees
2001-10	Failure of Central Sprinkler Company Model GB Series Fire Sprinkler Heads	06/28/01	All holders of licenses for nuclear power, research, and test reactors and fuel cycle facilities
2001-09	Main Feedwater System Degradation in Safety-Related ASME Code Class 2 Piping Inside the Containment of a Pressurized Water Reactor	06/12/01	All holders of operating licenses for pressurized water nuclear power reactors, except those who have permanently ceased operations and have certified that fuel has been permanently removed from the reactor vessel
2001-08 Supplement 1	Update on the Investigation of Patient Deaths in Panama, Following Radiation Therapy Overexposures	06/06/01	All Medical Licensees
2001-08	Treatment Planning System Errors Result in Deaths of Overseas Radiation Therapy Patients	06/01/01	All medical licensees
2001-07	Unescorted Access Granted Based on Incomplete and/or Inaccurate Information	05/11/01	All holders of nuclear reactor operating licenses who are subject to Section 73.56 of Title 10, of the Code of Federal Regulations (10 CFR 73.56), "Personnel Access Authorization Requirements of Nuclear Power Plants."