

REPORT REQUESTOR: BARTLETT, B.L.

\*\*\* ACTION REQUEST \*\*\*

Page: 1

A/R Type : CM  
Pri/Ctd : 35  
Request Org : ENPT  
Request Date: 11FEB98  
Requested By: PHELAN, S.M.  
Pend Reason :

A/R Number : A0156971  
A/R Status : COMPLT  
Status Date: 20APR00  
Last Update: 26APR00  
Print Date : 02MAY00

## A. Equipment Code Related Information.

Comp Nbr: Unit: 2 System: Type:  
FEG : 295.01 Desc: UNIT 2 CONTAINMENT  
Disp FEG: 295.01  
Unit Loc: Bldg: Elevation: Room No.: Safety Rel:  
A/R Tag?: N Tag Loc: N/A Maint. Cat.: P

A/R Desc: INVESTIGATE DEGRADED CONCRETE IN 2-HV-CEQ-2 FAN ROOM.

## B. Detail Description and Location of Problem.

DURING MATERIAL CONDITION WALKDOWN, SEVERELY DEGRADED  
CONCRETE COATING AND GROUT WITH LOOSE PIECES WERE FOUND  
AT THE TOP CORNER OF THE WEST WALL DIRECTLY OVER THE FAN  
HOUSING. (CONTINUED)  
THIS CONDITION DOES NOT IMPACT 2-HV-CEQ-2 OPERABILITY.  
THE COMPONENT NUMBER WAS USED ONLY TO DESIGNATE LOCATION.  
G. 295.01  
SENT TO IPSO FOR U2R ADD REVIEW  
NOT APPROVED FOR U2R97 PER ORB U2R99  
ASSIGNED NNPC BY NNSC  
ADDED TO U2R97 PER MT CM BACKLOG REVIEW  
C45329-01 PRINTED/ISSUED TO P. RICHARD VIA JAY NIYOGI  
C45329-01 REFILED DUE TO ENGINEERING FLAG  
C45329-01 REPRINTED/RE-ISSUED TO PHIL RICHARD VIA GFR  
C45329-01 SENT TO NRM 4/22/00

SMP	11FEB98
SMP	11FEB98
SMP	11FEB98
SMP	11FEB98
SMP	11FEB98
SMP	11FEB98
JAH	12FEB98
JAH	12FEB98
JAH	12FEB98
JMC	12FEB98
LCH	19DEC98
JMC	21OCT99
JMC	28FEB00
JMC	10APR00
JMC	26APR00

B/17