



**UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064**

September 20, 2001

Mr. J. V. Parrish
Chief Executive Officer
Energy Northwest
P.O. Box 968; MD 1023
Richland, Washington 99352-0968

SUBJECT: LICENSED OPERATOR POSITIVE ALCOHOL TEST

Dear Mr. Parrish,

On September 12, 2001, you reported in Event Report 38280, that one of your NRC-licensed senior reactor operators tested positive for alcohol on a fitness-for-duty test administered by your staff on September 12, 2001. In order to facilitate our review of this matter, we require information beyond what you have reported to date which is relevant to this matter. Therefore, we request that you provide, within 30 days after the date of this letter, answers to the questions listed in the enclosure and any other records or information you may have on this operator's fitness for duty. Any personal, proprietary, or safeguards information in your response should be contained in a separate attachment and appropriately marked. An affidavit required by 10 CFR 2.790(b) must accompany your response, where applicable.

You should determine whether the operator meets the requirements of 10 CFR 55.33(a)(1). You should ensure that (1) the operator meets the general health requirements of ANSI/ANS-3.4-1983, (2) the operator does not have a disqualifying condition under Section 5.3 of that standard, and (3) that documentation describing the designated physician's conclusion that the operator meets the requirements of ANSI/ANS-3.4-1983 is available for review by the NRC. If a conditional license is requested per 10 CFR 55.25, that condition should be documented on NRC Form 396 and transmitted to the NRC.

If you determine that the operator no longer meets the medical qualifications described in 10 CFR 55.33(a)(1), then, in accordance with 10 CFR 55.25, you must notify the NRC via letter of the operator's permanent incapacitation. For example, you must notify the NRC if you determine, based on your employee assistance program in consultation with your designated physician, that the operator can no longer meet the medical criteria of ANSI/ANS-3.4-1983.

The NRC will evaluate the information in your reply to this letter to determine if further action is warranted pursuant 10 CFR Parts 50 or 55. The information provided by you will be subject to the Privacy Act of 1974 and it will be maintained in the Privacy Act System of Records, NRC-16, "Facility Operator Licensees Records Files."

If you have any questions, please contact Anthony T. Gody, Chief, Operations Branch at (817) 860-8159. Your cooperation is appreciated.

Sincerely,

/RA/

Arthur T. Howell III, Director
Division of Reactor Safety

Docket: 50-397
License: NPF-21

Enclosure:
Licensed Operator Fitness-For-Duty
Questionnaire

cc w/enclosure:
Chairman
Energy Facility Site Evaluation Council
P.O. Box 43172
Olympia, Washington 98504-3172

Rodney L. Webring (Mail Drop PE08)
Vice President, Operations Support/PIO
Energy Northwest
P.O. Box 968
Richland, Washington 99352-0968

Greg O. Smith (Mail Drop 927M)
Vice President, Generation
Energy Northwest
P.O. Box 968
Richland, Washington 99352-0968

D. W. Coleman (Mail Drop PE20)
Manager, Regulatory Affairs
Energy Northwest
P.O. Box 968
Richland, Washington 99352-0968

Albert E. Mouncer (Mail Drop 1396)
General Counsel
Energy Northwest
P.O. Box 968
Richland, Washington 99352-0968

Energy Northwest

-3-

Paul Inserra (Mail Drop PE20)
Manager, Licensing
Energy Northwest
P.O. Box 968
Richland, Washington 99352-0968

Thomas C. Poindexter, Esq.
Winston & Strawn
1400 L Street, N.W.
Washington, D.C. 20005-3502

Bob Nichols
State Liaison Officer
Executive Policy Division
Office of the Governor
P.O. Box 43113
Olympia, Washington 98504-3113

Lynn Albin
Washington State Department of Health
P.O. Box 7827
Olympia, WA 98504-7827

Electronic distribution from ADAMS by RIV:
 Regional Administrator (**EWM**)
 DRP Director (**KEB**)
 DRS Director (**ATH**)
 Senior Resident Inspector (**GDR**)
 Branch Chief, DRP/E (**WBJ**)
 Senior Project Engineer, DRP/E (**GAP**)
 Dave Trimble, IOLB
 Laura Hurley, OB

C:\Program Files\Adobe\Acrobat 4.0\PDF Output\columbia gen station ffd po~.wpd

LA:OB	C:OB	C:DRPE	RIV:OE	C:IOLB	D:DRS
LAHurley	ATGody	WBJones	GSanborn	DTrimble	ATHowell
/RA/	/RA/	/RA/	/RA/	ATG for	/RA/
09/17/01	09/18/01	09/19/01	09/19/01	09/18/01	09/19 /01

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

ENCLOSURE

Licensed Operator Fitness-for-Duty Questionnaire

Energy Northwest is requested to provide the following information concerning the fitness-for-duty occurrence of September 12, 2001 (Event Report 38280), regarding the involved licensed operator:

1. Name and responsibilities of the operator.
2. A summary of the operator's entire fitness-for-duty testing history. Please include the dates and times the operator was tested, the reasons for the tests (i.e., random, for-cause, or follow-up), the results of the tests, and the dates that any tests were confirmed positive.
3. A detailed chronology (time line) associated with this event, including all the information developed as a result of your review of the event (e.g., the report documenting your review of this matter, summaries of interviews, etc.).
4. Whether the operator consumed alcoholic beverages within the protected area. If so, please provide the details of the circumstances surrounding such consumption.
5. Whether the operator was at the controls or supervising licensed activities while under the influence of alcohol. If so, please provide the details of the operator's performance of licensed duties while under the influence of alcohol.
6. Whether the operator was involved in procedural errors related to this occurrence. If so, please provide the details of the procedural errors and the consequences of the errors.
7. Your intentions with regard to the operator's resumption of duties under the 10 CFR Parts 50 and 55 licenses, including your plans for follow-up testing.
8. Any other relevant information, which will facilitate the NRC review of this matter.