

SAFEGUARDS INFORMATION

October 18, 2001

Southern Nuclear Operating Company, Inc.
ATTN: Mr. D. N. Morey
Vice President
P. O. Box 1295
Birmingham, AL 35201-1295

SAFEGUARDS INFORMATION REMOVED

SUBJECT: JOSEPH M. FARLEY NUCLEAR PLANT
NRC INSPECTION REPORT 50-348/01-10 AND 50-364/01-10

Dear Mr. Morey:

On August 10, 2001, the NRC completed an inspection at your Farley Nuclear Plant. This inspection was an examination of activities conducted under your license as they relate to safety and compliance with the Commission's rules and regulations and with the conditions of your license. Within these areas, the inspection consisted of a selected examination of procedures and representative records, observations of activities, and interviews with personnel. The enclosed inspection report presents the results of this inspection which were discussed on August 10, 2001, with Mr. Mike Stinson and other members of your staff.

Based on the results this inspection, the inspectors identified two findings of very low safety significance (Green) which were determined to be violations of NRC requirements. However, because of their very low safety significance and because you have entered them into your corrective action program, the NRC is treating these violations as Non-Cited Violations in accordance with Section VI.A.1 of the NRC's Enforcement Policy. If you deny these Non-Cited Violations, you should provide a response with the basis of your denial, within 30 days of the date of this inspection report, to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555-0001; with copies to the Regional Administrator, Region II; Director, Office of Enforcement, U.S. Nuclear Regulatory Commission, Washington, D.C. 20555-0001; and the NRC Resident Inspector at the Joseph M. Farley Nuclear Plant.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter without the Safeguards Information will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of

SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

SNC

2

NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/NRC/ADAMS/index.html> (the Public Electronic Reading Room).

Sincerely,

/RA/

Kenneth P. Barr, Chief
Plant Support Branch
Division of Reactor Safety

Docket Nos.: 50-348, 50-364
License Nos.: NPF-2, NPF-8

Enclosure: NRC Inspection Report 50-348/01-10;
50-364/01-10
(Contains Safeguards Information)

PUBLIC DOCUMENT (circle one): YES NO

OFFICE	RII:DRS	RII:DRP	RII:DRP	RII:DRS	RII:EICS	RII:DRS	
SIGNATURE							
NAME	D Holman	C Rapp	S Cahill	K Barr	A Boland		
DATE	10/18/01	NA	10/17/01	10/18/01	10/18/01		
E-MAIL COPY?	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO

OFFICIAL RECORD COPY

DOCUMENT NAME:

SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

SNC

3

cc w/encl:

M. J. Ajluni, Licensing
Services Manager, B-031
Southern Nuclear Operating
Company, Inc.
42 Inverness Center Parkway
Birmingham, AL 35201-1295

L. M. Stinson
General Manager, Farley Plant
Southern Nuclear Operating
Company, Inc.
P. O. Box 1295
Birmingham, AL 35201-1295

cc w/Inspection Summary:
J. D. Woodard
Executive Vice President
Southern Nuclear Operating
Company, Inc.
P. O. Box 1295
Birmingham, AL 35201-1295

State Health Officer
Alabama Department of Public Health
RSA Tower - Administration
Suite 1552
P. O. Box 303017
Montgomery, AL 36130-3017

M. Stanford Blanton
Balch and Bingham Law Firm
P. O. Box 306
1710 Sixth Avenue North
Birmingham, AL 35201

William D. Oldfield
SAER Supervisor
Southern Nuclear Operating Company
P. O. Box 470
Ashford, AL 36312

Distribution w/Inspection Summary:
DRPM/PSGB w/encl
DOCDESK IE04, 016

SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

U.S. NUCLEAR REGULATORY COMMISSION

REGION II

Docket Nos.: 50-348 and 50-364

License Nos.: NPF-2 and NPF-8

Report No.: 50-348/01-10 and 50-364/01-10

Licensee: Southern Nuclear Operating Company, Inc. (SNC)

Facility: Farley Nuclear Plant, Units 1 and 2

Location: 7388 N. State Highway 95
Columbia, AL 36319

Dates: August 6 to August 10, 2001

Inspectors: D. Holman, Physical Security Inspector (Lead)
D. Thompson, Physical Security Inspector
J. Wallo, Physical Security Inspector

Approved by: Kenneth P. Barr, Chief
Plant Support Branch
Division of Reactor Safety

SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

SUMMARY OF FINDINGS

IR 05000348-01-10, IR 05000364-01-10, on 08/6/2001 - 08/10/2001, Southern Nuclear Operating Company, Joseph M. Farley Nuclear Plant, Units 1 & 2, Security Inspection Report.

This inspection report covers a 1-week period of inspection conducted by region based security inspectors. The inspectors identified two Green findings which were Non-Cited Violations. The significance of inspector findings is indicated by their color (Green, White, Yellow, or Red) using Inspection Manual Chapter 0609, Significance Determination Process.

Inspector Identified Findings

Cornerstone: Physical Protection

- a. Green. A Non-Cited Violation (NCV) was identified when a security officer failed to properly search several individuals prior to allowing them unescorted access to the protected area (PA). Requirements violated were established in the Farley Physical Security Plan and implementing procedures.

While the risk was low in this case, this issue was identified as more than a minor finding because granting site access to individuals who have not been properly searched can have a credible impact on safety. Additionally, the granting of access to improperly searched individuals can be viewed as a precursor to a significant event.

- b. Green. An NCV was identified in that compensatory measures for suppressed tamper alarms associated with vital area doors, alarm panel doors and CCTV alarm panel doors were not implemented in accordance with the Farley Physical Security Plan.

While the risk was low in this case, this issue was identified as more than a minor finding because inoperable intrusion detection system tamper alarms leave the affected system component susceptible to malevolent manipulation.

SAFEGUARDS INFORMATION