Docket No.: 50-413

Mr. H. B. Tucker, Vice President Nuclear Production Department Duke Power Company 422 South Church Street Charlotte, North Carolina 28242

0 1 MAY 1986

Dear Mr. Tucker:

Subject: Technical Specification Correction

My letter of April 24, 1986, transmitted Amendment No. 7 to Facility Operating License NPF-35 for the Catawba Nuclear Station, Unit 1.

One of the Technical Specification pages attached to that amendment contained a typographical error. Enclosed is a corrected page.

Please replace page 3/4 8-6 in Amendment 7 with the enclosed corrected page.

Sincerely,

151

Kahtan Jabbour, Project Manager PWR Project Directorate #4 Division of PWR Licensing-A

Enclosure: As stated

cc: See next page

DISTRIBUTION:

Docket File

NRC PDR

Local PDR

PRC System

NSIC

PWR#4 Rdg

MDuncan

BJYoungblood Rdg

KJabbour

**OELD** 

LHarmon

EJordan

**BGrimes** 

**JPartlow** 

TBarnhart (4)

**WJones** 

ACRS (10)

OPA

**LFMB** 

PWR#4/PPWR-A MBuncan/mac 04/3/)/86 PWR#4/DPWR-A KJabbour 04/20/86

**\** 

PWR#4/DPWR-A for BJYoungblood 04/30 /86

8605080397 860501 PDR ADDCK 05000413 PDR PDR

4

Mr. H. B. Tucker Duke Power Company

cc: William L. Porter, Esq. Duke Power Company P.O. Box 33189 Charlotte, North Carolina 28242

J. Michael McGarry, III, Esq. Bishop, Liberman, Cook, Purcell and Reynolds 1200 Seventeenth Street, N.W. Washington, D. C. 20036

North Carolina MPA-1 Suite 600 3100 Smoketree Ct. P.O. Box 29513 Raleigh, North Carolina 27626-0513

Mr. C. D. Markham
Power Systems Division
Westinghouse Electric Corp.
P.O. Box 355
Pittsburgh, Pennsylvania 15230

NUS Corporation 2536 Countryside Boulevard Clearwater, Florida 33515

Mr. Jesse L. Riley, President Carolina Environmental Study Group 854 Henley Place Charlotte, North Carolina 28208

Richard P. Wilson, Esq. Assistant Attorney General S.C. Attorney General's Office P.O. Box 11549 Columbia, South Carolina 29211

Piedmont Municipal Power Agency 100 Memorial Drive Greer, South Carolina 29651

Mark S. Calvert, Esq. Bishop, Liberman, Cook, Purcell & Reynolds 1200 17th Street, N.W. Washington, D. C. 20036

Brian P. Cassidy, Regional Counsel Federal Emergency Management Agency, Region I J. W. McCormach POCH Boston, Massachusetts 02109 Catawba Nuclear Station

North Carolina Electric Membership Corp. 3333 North Boulevard P.O. Box 27306 Raleigh, North Carolina 27611

Saluda River Electric Cooperative, Inc. P.O. Box 929 Laurens, South Carolina 29360

Senior Resident Inspector Route 2, Box 179N York, South Carolina 29745

Regional Administrator, Region II U.S. Nuclear Regulatory Commission, 101 Marietta Street, NW, Suite 2900 Atlanta, Georgia 30323

Robert Guild, Esq. 2759 Rosewood Drive Columbia, South Carolina 29205

Palmetto Alliance 2759 Rosewood Drive Columbia, South Carolina 29205

Karen E. Long Assistant Attorney General N.C. Department of Justice P.O. Box 629 Raleigh, North Carolina 27602

Spence Perry, Esquire Associate General Counsel Federal Emergency Management Agency Room 840 500 C Street Washington, D. C. 20472

Mr. Michael Hirsch Federal Emergency Management Agency Office of the General Counsel Room 840 500 C Street, S.W. Washington, D. C. 20472

## - 2 - Catawba (amendments)

cc: Mr. Heyward G. Shealy, Chief Bureau of Radiological Health South Carolina Department of Health and Environmental Control 2600 Bull Street Columbia, South Carolina 29201

County Manager of York County York County Courthouse York, South Carolina 29745

Attorney General P.O. Box 11549 Columbia, South Carolina 29211

## SURVEILLANCE REQUIREMENTS (Continued)

during this test. Within 5 minutes after completing this 24-hour test, perform Specification 4.8.1.1.2g.6)b);\* \*\*

- 8) Verifying that the auto-connected loads to each diesel generator do not exceed 5750 kW;\*\*
- 9) Verifying the diesel generator's capability to:\*\*
  - a) Synchronize with the offsite power source while the - generator is loaded with its emergency loads upon a simulated restoration of offsite power,
  - b) Transfer its loads to the offsite power source, and
  - c) Be restored to its standby status.
- 10) Verifying that with the diesel generator operating in a test mode, connected to its bus, a simulated Safety Injection signal overrides the test mode by: (1) returning the diesel generator to standby operation, and (2) automatically energizing the emergency loads with offsite power;\*\*
- 11) Verifying that the fuel transfer valve transfers fuel from each fuel storage tank to the day tank of each diesel via the installed cross-connection lines;
- 12) Verifying that the automatic load sequence timer is OPERABLE with the interval between each load block within the tolerances given in Table 4.8-2;
- 13) Verifying that the voltage and diesel speed tolerances for the accelerated sequencer permissives are  $92.5 \pm 1\%$  and 98 + 1%, respectively, with a minimum time delay of  $2 \pm 0.2$  s; and
- 14) Verifying that the following diesel generator lockout features prevent diesel generator starting only when required:
  - a) Turning gear engaged, or
  - b) Maintenance mode.

<sup>\*</sup>If Specification 4.8.1.1.2g.6)b) is not satisfactorily completed, it is not necessary to repeat the preceding 24-hour test. Instead, the diesel generator may be operated at greater than or equal to 5600 kW but less than or equal to 5750 kW for 1 hour or until operating temperature has stabilized.

<sup>\*\*</sup>This surveillance need not be performed until prior to entering HOT SHUTDOWN following the Unit 1 first refueling.