

Region I  
NMSS Licensee Event Report

License No. 07-28762-02G

Docket No. 03002988

MLER-RI 2001-057

LICENSEE: AGILENT

EVENT DESCRIPTION NOTICE OF GENERAL LICENSE DEVICES W/HIGH REMOVABLE ACTIVITY

EVENT DATE \_\_\_\_\_ REPORT DATE 11/16/01

1. REPORTING REQUIREMENT

- |  |   |
|--|---|
| <input type="checkbox"/> 10 CFR 20.2201 Theft or Loss        | <input type="checkbox"/> 10 CFR 35.33 Misadministration |
| <input type="checkbox"/> 10 CFR 20.2203 30 Day Report        | <input type="checkbox"/> License Condition              |
| <input type="checkbox"/> 10 CFR 30.50 Report                 |   |
| <input checked="" type="checkbox"/> Other <u>10 CFR 31.5</u> |   |

2. REGION I RESPONSE

- |   |                                       |
|---|---------------------------------------|
| <input type="checkbox"/> Immediate Site Inspection                    | Inspector/Date _____                  |
| <input type="checkbox"/> Special Inspection                           | Inspector/Date _____                  |
| <input type="checkbox"/> Telephone Inquiry                            | Inspector/Date _____                  |
| <input type="checkbox"/> Preliminary Notification                     | <input type="checkbox"/> Daily Report |
| <input checked="" type="checkbox"/> Information Entered on the RI Log |                                       |
| <input checked="" type="checkbox"/> Review at Next Routine Inspection | <u>of 07-28762-026 license</u>        |
| <input type="checkbox"/> Report Referred to _____                     |                                       |

3. REPORT EVALUATION

- |  |   |
|--|---|
| <input checked="" type="checkbox"/> Description of Event   | <input type="checkbox"/> Corrective Actions                                   |
| <input checked="" type="checkbox"/> Levels of RAM Involved | <input type="checkbox"/> Calculation Adequate                                 |
| <input type="checkbox"/> Cause of Event                    | <input type="checkbox"/> Letter to Licensee Requesting Additional Information |


4. SPECIAL INSTRUCTIONS OR COMMENTS

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Completed By: [Signature] Date 11/21/01

Reviewed By: [Signature] Date 11/26/2001

RECEIVED  
REGION I

 **Agilent Technologies**  
2850 Centerville Road  
Wilmington, DE 19808

2001 NOV 16 PM 2: 49

Division of Nuclear Materials Safety  
U.S. Nuclear Regulatory Commission  
Region I  
475 Allendale Road,  
King of Prussia, PA 19406

Re: Notice of General License devices with high removable activity (NRC License 07-28762-02G)

November 14, 2001


Dear Sir or Madam,

Per the requirements of 10 CFR 31.5, I am notifying your office of a general license device from which we have obtained removable activity wipes in excess of 0.005  $\mu\text{Ci}$ . The cell was returned from a customer overseas for refurbishing or disposal. The cell was evaluated by support engineering and the customer has been contacted for further information about their cell's history. The cell supplier is being notified of the failure and it will be scrapped.

<u>Serial #</u>	<u>Model #</u>	<u>Activity (<math>\mu\text{Ci}</math>)</u>
N0207	G1533	0.013

Please contact me at 302-633-8262 if there are any questions.

Thank you,



David S. Bennett  
Radiation Safety Officer

 **NMSS-11**