

## UNITED STATES NUCLEAR REGULATORY COMMISSION

## **REGION IV**

## 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

November 28, 2001

Mr. Joe Muller
Director of Regulatory Compliance
Dairygold, Inc.
635 Elliott Avenue, West
P.O. Box 79007
Seattle, Washington 98119

SUBJECT: NRC INSPECTION REPORT 999-90004/2001-005

Dear Mr Muller:

This letter refers to the inspection conducted on October 25, 2001, at your facility in Caldwell, Idaho. This inspection was an examination of activities conducted under the general license, pursuant to 10 CFR 31.5, as they relate to safety and compliance with the Commission's rules and regulations and with the conditions of your license. Specifically, the inspector reviewed Dairygold, Inc.'s possession, use and subsequent disposal of a Kay Ray density transmitter device containing cesium-137 as a sealed source. Within these areas, the inspection consisted of selected examination of representative records and interviews with personnel. At the conclusion of the onsite inspection, the inspection results were discussed with Mr. Dennis Agenbroad, Assistant Plant Manager.

Within the scope of this inspection no violations or deviations were identified; therefore, no response to this letter is required.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure(s), and your response will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <a href="http://www.nrc.gov/NRC/ADAMS/index.html">http://www.nrc.gov/NRC/ADAMS/index.html</a> (the Public Electronic Reading Room).

Should you have any questions concerning this letter, please contact Mr. Larry Donovan at (817) 860-8140 or the undersigned at (817) 860-8287.

Sincerely,

/RA/

Mark R. Shaffer, Chief Nuclear Materials Inspection Branch

Docket No.: 999-90004 License No.: 10 CFR 31.5

Enclosure: As stated

cc w/enclosure: Idaho Radiation Control Program Director Oregon Radiation Control Program Director bcc w/enclosure (via ADAMS distrib):

**EWMerschoff** 

DDChamberlain

LLHowell

MRShaffer

CLCain

LDonovan

**NMIB** 

MIS System RIV Nuclear Materials File - 5<sup>th</sup> Floor

DOCUMENT NAME:s\dnms\nmib\donovan\1900045.wpd final:R:\\_dnms\

RIV:DNMS:NMIB	C:NMIB
LDonovan	MRShaffer
/RA/	/RA/
11/19/01	11/28/01