

Form TI-1 Case Resolution

Case Status	<input type="checkbox"/> Open	<input checked="" type="checkbox"/> Closed
RCODE: <u>54189</u>		
Region: <u>1</u>		
OLD - Complete Name, Address, Contact, Phone Number: Adobe Mining Company Road 3 Grove City, PA 16127 Norman Stouffer		
NEW - Complete Name, Address, Contact, Phone Number: None		
Agreement State Licensee? (Double Check)	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Moved to an Agreement State?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Describe Follow-up: (Telephone, Internet, Chamber of Commerce, Other) Infoseek search for "Adobe Mining" found documents concerning reclamation activities of mining sites abandoned by the defunct Adobe Mining Company. Most of the reclamation work was being performed by Amerikohl Mining Inc. for the value of the surety. I contacted an Amerikohl Mining representative who reported that Adobe had two sites in Grove City, both coal tipples. He said that at the end, Adobe had sold all equipment on the sites as scrap. When his company started work on the sites some time later, all that was left were the concrete footings.		
Describe Communication with Registration Vendor:		
Vendor Follow-up Action:		
Final Action Taken:		
Cause of Bad Address/Lesson Learned: Site abandoned by financially distressed company. At the point the company was selling its equipment for scrap it was unlikely to expend the money to dispose of the gauges properly.		

Form TI-2: Device Information

RCODE: <u>54189</u>								
ID	Model Number	Serial Number	Isotope	Activity (mCi)	Sold Date	Vendor	Status (A or N)	Comments
1	5202	000000	¹³⁷ Cs	200	19903	L01105	N	Probably scrapped Probably scrapped
2	5201	000000	¹³⁷ Cs	100	19903	L01105	N	
For additional GLD's received by the licensee identified during the inspection:								
ID	Model Number	Serial Number	Isotope	Activity	Sold Date	Vendor	How obtained	Comments

Status Codes:

- A - Source accounted for
- N - Source not accounted for

Form TI-3: General Licensee Inspection Documentation

RCODE: <u>54189</u>	
General Licensee Information:	
	Check Box if Current Complete Name, Mailing Address, Contact, and Phone Number is Same as Provided by ORNL. If not, include correct information below:
	None
Results of inspection: (check the appropriate boxes)	
	The general licensee of record is located at the address of record and
	all GLD are accounted for
	<u>not</u> all GLD are accounted for
	The general licensee of record is <u>not</u> located at the address of record, however GLD are being used under new ownership at the address of record and
	all GLD are accounted for
	<u>not</u> all GLD are accounted for
	The general licensee of record is <u>not</u> located at the address of record, however they are using GLD at another location and
	all GLD are accounted for
	<u>not</u> all GLD are accounted for;
X	Neither the general licensee of record nor the facility operated by the general licensee are located at the address of record and the site has been abandoned or is being used for an alternate purpose.
	Other: (explain)
Gauge Information:	
ID	For each gauge for which status is unaccounted for (see last column of Form TI-2), provide any conclusions about location of the gauge:
all	Probably went to a scrap metal dealer on other equipment being scrapped.

The general licensee abandoned the facility at which the sources were installed. Information generated during the inspection suggests the licensee scrapped all equipment on the site before abandoning it. We conclude that the sources were properly taken away as scrap with the equipment to which they were attached.

Inspector: Keith Brown, Health Physicist
Nuclear Materials Safety Branch 2

Approved By: John D. Kinneman, Chief
Nuclear Materials Safety Branch 2