

Form TI-1 Case Resolution

Case Status	<input type="checkbox"/> Open	<input checked="" type="checkbox"/> Closed
RCODE: <u>3727</u>		
Region: <u>1</u>		
OLD - Complete Name, Address, Contact, Phone Number: Asarco, Inc. Route 70 Lakehurst, NJ 08733		
NEW - Complete Name, Address, Contact, Phone Number: Asarco, Inc. 180 Maiden Lane New York, NY 10038 Contact: Mike Varner, VP, Env. 212-510-2000		
Agreement State Licensee? (Double Check)	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Moved to an Agreement State?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Describe Follow-up: (Telephone, Internet, Chamber of Commerce, Other) John Lord (732-922-6100) formerly of Asarco, and consultant to Heritage Minerals. According to Mr. Lord, the gauges were in use at an ilminite mine. In this type of mining, a pond is dug and filled. A barge dredges the pond and sends the removed material to the separation plant (which is frequently on barges as well). Mr. Lord was hired as a consultant to help with the sale of the site to Heritage Minerals around 1982. He reported that at that time the barge was dry docked and the gauges were gone. From descriptions of people who were there when the gauges were removed, he believed they were returned to the manufacturer.		
Describe Communication with Registration Vendor: None		
Vendor Follow-up Action:		
Final Action Taken:		
Cause of Bad Address/Lesson Learned:		

Form TI-2: Device Information

RCODE: __3727__								
ID	Model Number	Serial Number	Isotope	Activity (mCi)	Sold Date	Vendor	Status (A or N)	Comments
1			Unknown	Unknown	Unknown	Unknown	A	
For additional GLD's received by the licensee identified during the inspection:								
ID	Model Number	Serial Number	Isotope	Activity	Sold Date	Vendor	How obtained	Comments

Status Codes:

A - Source accounted for

N - Source not accounted for

Form TI-3: General Licensee Inspection Documentation

RCODE: <u>3727</u>	
General Licensee Information:	
<input type="checkbox"/>	Check Box if Current Complete Name, Mailing Address, Contact, and Phone Number is Same as Provided by ORNL. If not, include correct information below:
<input type="checkbox"/>	
Results of inspection: (check the appropriate boxes)	
<input type="checkbox"/>	The general licensee of record is located at the address of record and
<input type="checkbox"/>	all GLD are accounted for
<input type="checkbox"/>	<u>not</u> all GLD are accounted for
<input type="checkbox"/>	The general licensee of record is <u>not</u> located at the address of record, however GLD are being used under new ownership at the address of record and
<input type="checkbox"/>	all GLD are accounted for
<input type="checkbox"/>	<u>not</u> all GLD are accounted for
<input type="checkbox"/>	The general licensee of record is <u>not</u> located at the address of record, however they are using GLD at another location and
<input type="checkbox"/>	all GLD are accounted for
<input type="checkbox"/>	<u>not</u> all GLD are accounted for;
X	Neither the general licensee of record nor the facility operated by the general licensee are located at the address of record and the site has been abandoned or is being used for an alternate purpose.
<input type="checkbox"/>	Other: (explain)
Gauge Information:	
ID	For each gauge for which status is unaccounted for (see last column of Form TI-2), provide any conclusions about location of the gauge:
<input type="checkbox"/>	
<input type="checkbox"/>	

The file included no information concerning the gauges. Based on the information we developed, we conclude that the gauges at the site were disposed properly.

Inspector: Keith Brown, Health Physicist
Nuclear Materials Safety Branch 2

Approved By: John D. Kinneman, Chief
Nuclear Materials Safety Branch 2