

10/26/00

I met with Ted Sullivan, Emmet Murphy, and Ken Karwoski of EMCB on 10/26/00 to discuss the needed revisions to baseline and supplementary procedures for ISI including SG tube inspections. The following actions were identified:

1. IP 71111.08 requires revision to incorporate regional comments, SG tube inspection, and any comments EMCB may have on the existing procedure. The increase in inspection resources for PWRs should be estimated. A draft revision will be prepared by EMCB.
2. Supplementary procedures IP 73753 (Inservice Inspection) and IP 50002 (Steam Generators) also need to be reviewed and revised by EMCB.
3. Don Hickman is responsible for PIs in IIPB. The draft proposals for the need for and specifics of SG tube PIs will be handled by him.
4. IIPB will coordinate review of revised procedures by the regions and resolution of regional comments, and issue the procedures.
5. EMCB will include the above activities in the SG action plan in consultation with IIPB.

J/134