

## December 28, 2001

L-2001-285 10 CFR 50.36 10 CFR 50.4

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

Re:

St. Lucie Unit 2

Docket No. 50-389 Special Report

Steam Generator Tube Plugging Report

This letter is being sent pursuant to St. Lucie Unit 2 Technical Specification 4.4.5.5.a. The following tubes were plugged during the Unit 2 refueling outage (SL2-13).

Steam Generator 2A - 129 Steam Generator 2B - 232

Cumulative tubes plugged during this outage and previous outages:

Steam Generator 2A - 474 Steam Generator 2B - 539

Should you have any questions on this information, please contact us.

Very truly yours,

Donald E. Jernigan Vice President St. Lucie Plant

**DEJ/GRM**