

PRIORITY **Rush**

DISPOSITION OF THE ORIGINAL DOCUMENT WILL BE TO THE TRANSMITTAL SIGNATURE UNLESS RECIPIENT IS OTHERWISE IDENTIFIED BELOW

- 1) 02049 NGO PRA MANAGER EC08I
- 2) 02188 NPA MANAGER EC05N
- 3) 02467 ELECT. LICENSING LIBRARY EC050
- 4) 02532 MCG NRC INSP MG-ADMIN MAIL RM
- 5) 02546 WC LIBRARY - MG01WC
- 6) 03044 MCG DOC CNTRL MISC MAN MGO5DM
- 7) 03102 H L MASSEY OPS PROC GP MG03OT
- 8) 03379 D E CALDWELL MG01MM
- 9) 03447 HARRY J SLOAN MG01RP
- 10) 03614 MCG OPS PROCEDURE GP MG01OP
- 11) 03744 OPS TRNG MGR. MG03OT
- 12) 03759 U S NUCLEAR REG WASH, DC
- 13) 04771 E E HITE EC09E
- 14) 04809 MCG PLANT ENG. LIBR. MG05SE
- 15) 05160 P T VU MG01RC

**Duke Power Company  
DOCUMENT TRANSMITTAL FORM**

**REFERENCE**

MCGUIRE NUCLEAR STATION  
SELECTED LICENCEE COMMITMENTS  
MANUAL (SLC)

Page 2 of 3

Date: 12/06/01

Document Transmittal #: DUK013400056

QA CONDITION  Yes  No

OTHER ACKNOWLEDGEMENT REQUIRED  Yes

IF QA OR OTHER ACKNOWLEDGEMENT REQUIRED, PLEASE ACKNOWLEDGE RECEIPT BY RETURNING THIS FORM TO:

Duke Power Company  
P.O. Box 12700  
Document Management MG01 MOD  
Hagers Ferry Road  
Huntersville, N.C. 28078

Rec'd By \_\_\_\_\_

Date \_\_\_\_\_

| DOCUMENT NO                              | QA COND | REV #/ DATE  | DISTR CODE | 1  | 2  | 3  | 4  | 5  | 6  | 7  | 8  | 9  | 10 | 11 | 12 | 13 | 14 | 15 | TOTAL |
|--|---------|--------------|------------|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|-------|
| SELECTED LICENSEE COMMITMENT MANUAL LOEP | NA      | 015 12/03/01 | MADM-03A   | V1 | V1 | V1 | V1 | V1 | V1 | V1 | V1 | V1 | V1 | V2 | V8 | V1 | V2 | V1 | 51    |
| SLC 16.9.16                              | NA      | 015 12/03/01 |            |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |       |
|  | NA      | 019 12/03/01 |            |    |    |    |    |    |    |    |    |    |    |    |    |    |    |    |       |

REMARKS: PLEASE UPDATE YOUR MANUAL ACCORDINGLY

H B BARRON, JR.  
VICE PRESIDENT  
MCGUIRE NUCLEAR STATION

BY:

B C BEAVER MG01RC    BCB/CMK **SBC**

10001

December 3, 2001

MEMORANDUM

To: All McGuire Nuclear Station Selected Licensee Commitments (SLC) Manual Holders

Subject: McGuire SLC Manual Update

Please revise your copy of the manual as follows:

REMOVE

INSERT

List of Affected Sections Revision 14  
SLC 16.9.16 Revision 0

List of Affected Sections Revision 15  
SLC 16.9.16 Revision 19

**Revision numbers may skip numbers due to Regulatory Compliance Filing System.**

Please call me if you have questions

Bonnie Beaver  
Regulatory Compliance  
875-4180

A001

## SLC LIST OF AFFECTED SECTIONS

| SECTION | REVISION NUMBER | DATE     |
|---------|-----------------|----------|
| 16.1    | REVISION 0      | 12/14/99 |
| 16.2    | REVISION 0      | 12/14/99 |
| 16.3    | REVISION 0      | 12/14/99 |
| 16.4    | Not Issued      |          |
| 16.5.1  | REVISION 0      | 12/14/99 |
| 16.5.2  | REVISION 0      | 12/14/99 |
| 16.5.3  | REVISION 0      | 12/14/99 |
| 16.5.4  | REVISION 7      | 09/14/00 |
| 16.5.5  | REVISION 0      | 12/14/99 |
| 16.5.6  | REVISION 0      | 12/14/99 |
| 16.5.7  | REVISION 0      | 12/14/99 |
| 16.5.8  | REVISION 0      | 12/14/99 |
| 16.5.9  | REVISION 0      | 12/14/99 |
| 16.5.10 | REVISION 0      | 12/14/99 |
| 16.6.1  | REVISION 0      | 12/14/99 |
| 16.6.2  | REVISION 0      | 12/14/99 |
| 16.6.3  | REVISION 0      | 12/14/99 |
| 16.7.1  | REVISION 0      | 12/14/99 |
| 16.7.2  | REVISION 16     | 9/26/01  |
| 16.7.3  | REVISION 0      | 12/14/99 |
| 16.7.4  | REVISION 1      | 4/11/00  |
| 16.7.5  | REVISION 0      | 12/14/99 |
| 16.7.6  | REVISION 0      | 12/14/99 |
| 16.7.7  | REVISION 0      | 12/14/99 |
| 16.7.8  | REVISION 0      | 12/14/99 |
| 16.7.9  | REVISION 0      | 12/14/99 |
| 16.7.10 | REVISION 0      | 12/14/99 |
| 16.8.1  | REVISION 2      | 4/11/00  |
| 16.8.2  | REVISION 0      | 12/14/99 |
| 16.8.3  | REVISION 2      | 4/11/00  |
| 16.9.1  | REVISION 10     | 1/29/01  |
| 16.9.2  | REVISION 5      | 5/24/00  |
| 16.9.3  | REVISION 0      | 12/14/99 |
| 16.9.4  | REVISION 1      | 03/02/00 |
| 16.9.5  | REVISION 0      | 12/14/99 |
| 16.9.6  | REVISION 0      | 12/14/99 |
| 16.9.7  | REVISION 14     | 7/26/01  |
| 16.9.8  | REVISION 0      | 12/14/99 |
| 16.9.9  | REVISION 13     | 2/26/01  |
| 16.9.10 | REVISION 13     | 2/26/01  |
| 16.9.11 | REVISION 13     | 2/26/01  |
| 16.9.12 | REVISION 13     | 2/26/01  |
| 16.9.13 | REVISION 13     | 2/26/01  |
| 16.9.14 | REVISION 13     | 2/26/01  |
| 16.9.15 | REVISION 4      | 6/20/00  |
| 16.9.16 | REVISION 19     | 12/03/01 |
| 16.9.17 | REVISION 0      | 12/14/99 |

## SLC LIST OF AFFECTED SECTIONS

| SECTION  | REVISION NUMBER | DATE     |
|----------|-----------------|----------|
| 16.9.18  | REVISION 0      | 12/14/99 |
| 16.9.19  | REVISION 0      | 12/14/99 |
| 16.9.20  | REVISION 8      | 11/30/00 |
| 16.9.21  | REVISION 0      | 12/14/99 |
| 16.9.22  | REVISION 0      | 12/14/99 |
| 16.9.23  | Not Issued      |          |
| 16.9.24  | REVISION 15     | 9/26/01  |
| 16.10.1  | REVISION 0      | 12/14/99 |
| 16.11.1  | REVISION 9      | 2/1/01   |
| 16.11.2  | REVISION 9      | 2/1/01   |
| 16.11.3  | REVISION 0      | 12/14/99 |
| 16.11.4  | REVISION 0      | 12/14/99 |
| 16.11.5  | REVISION 0      | 12/14/99 |
| 16.11.6  | REVISION 0      | 12/14/99 |
| 16.11.7  | REVISION 12     | 3/14/01  |
| 16.11.8  | REVISION 0      | 12/14/99 |
| 16.11.9  | REVISION 0      | 12/14/99 |
| 16.11.10 | REVISION 0      | 12/14/99 |
| 16.11.11 | REVISION 0      | 12/14/99 |
| 16.11.12 | REVISION 0      | 12/14/99 |
| 16.11.13 | REVISION 0      | 12/14/99 |
| 16.11.14 | REVISION 0      | 12/14/99 |
| 16.11.15 | REVISION 0      | 12/14/99 |
| 16.11.16 | REVISION 1      | 4/11/00  |
| 16.11.17 | REVISION 1      | 4/11/00  |
| 16.11.18 | REVISION 0      | 12/14/99 |
| 16.11.19 | REVISION 0      | 12/14/99 |
| 16.11.20 | REVISION 0      | 12/14/99 |
| 16.12.1  | REVISION 0      | 12/14/99 |
| 16.12.2  | REVISION 0      | 12/14/99 |
| 16.13.1  | REVISION 0      | 12/14/99 |
| 16.13.2  | REVISION 0      | 12/14/99 |
| 16.13.3  | REVISION 0      | 12/14/99 |
| 16.14.1  | REVISION 0      | 12/14/99 |



REMEDIAL ACTIONS (continued)

| CONDITION   | REQUIRED ACTION  | COMPLETION TIME |
|---|--|-----------------|
| C. (continued).   | C.2 Prepare and submit a Special Report to NRC providing a record of the amount and the cumulative time that the temperature in the affected area exceeded the limit and an analysis to demonstrate continued operability of the affected equipment. | 30 days         |
| D. Diesel Generator Room temperature not within limits. | D.1 Initiate actions to restore Diesel generator Room temperature to within limits.<br><br><u>AND</u>  | Immediately     |
|   | D.2 Declare Diesel Generator inoperable.<br><br><u>AND</u>   | Immediately     |
|   | D.3 Initiate an engineering evaluation to determine the effect of the off-limit temperature on Diesel Generator Battery OPERABILITY if room temperature is < 55°F and Diesel Generator is not in service.  | Immediately     |

TESTING REQUIREMENTS

| TEST  | FREQUENCY |
|---|-----------|
| TR 16.9.16.1 Verify temperature in each of the areas shown in Table 16.9.16-1 is within limits. | 12 hours  |

TABLE 16.9.16-1

AREA TEMPERATURE MONITORING

| AREA                                     | TEMPERATURE LIMIT (°F)   |
|--|--------------------------|
| 1. Containment Spray Pump Rooms          | 145                      |
| 2. Miscellaneous Terminal Cabinets       |                          |
| a. TB208-209 (Turbine Building Unit 1)   | 150                      |
| b. TB496 (Fuel Building Unit 1)          | 150                      |
| c. TB1208-1209 (Turbine Building Unit 2) | 150                      |
| d. TB1496 (Fuel Building Unit 2)         | 150                      |
| 3. Residual Heat Removal Pump Rooms      | 145                      |
| 4. Diesel Generator Rooms                | $\geq 55$ and $\leq 125$ |
| 5. Spent Fuel Pool Cooling Pump Room     | 145                      |

## BASES

The area temperature limitations ensure that safety-related equipment will not be subjected to temperatures in excess of their environmental qualification temperatures. Exposure to excessive temperatures may degrade equipment and can cause a loss of its OPERABILITY. The Diesel Generator is declared inoperable immediately if the room temperature is outside its limits because various equipment within the room are only qualified for a specific temperature limit. The OPERABILITY evaluation associated with the restoration of the Diesel Generator to OPERABLE status will consider the effect of the off-limit temperature on the Diesel Generator. Required Action D.3 ensures the effect of the off-limit temperature on the Diesel Generator Batteries is evaluated. The temperature limits include an allowance for instrument error of 3.9°F.

Miscellaneous Terminal Cabinets TB208 (TB1208) and TB209 (TB1209) contain circuits associated with the function of closing the main feedwater control valves CF17, 20, 23 and 32 and main feedwater bypass valves CF104, 105, 106 and 107 on safety injection, Hi Hi S/G level, and Lo Tavg coincident with Rx trip. These cabinets also include relays used to forward the signal for main feedwater pump trip on turbine trip. TB208 is A train and TB209 is B train.

Miscellaneous Terminal Cabinets TB208 and TB1208 also contain the AMSAC inputs from main feedwater control valves CF17, 20, 23 and 32 limit switches.

Miscellaneous Terminal Cabinets TB496 (TB1496) contain circuits for IASV5080 which closes on phase A isolation to separate the air reservoir for the upper Containment Air lock from the VI system.

## REFERENCES

- MCC-1211.00-00-0004, Diesel Generator Ventilation Calculation.
- TAC Sheet MCTC-1579-VD.S001-01
- PIPs M93-0004, M94-0013, and M00-1248.