



Entergy Operations, Inc.
River Bend Station
5485 U.S. Highway 61
P. O. Box 220
St. Francisville, LA 70775
Tel 225 336 6225
Fax 225 635 5068

Rick J. King
Director
Nuclear Safety Assurance

November 14, 2001

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Subject: Monthly Operating Report
River Bend Station
Docket No. 50-458
License No. NPF-47

File No.: G9.5, G4.25

RBG-45870
RBF1-01-0258

Ladies and Gentlemen:

In accordance with River Bend Station Technical Specification 5.6.4, enclosed is the Monthly Operating Report for October 2001.

Sincerely,

A handwritten signature in cursive script, appearing to read "Rick J. King".

RJK/dhw
enclosure

A001

Monthly Operating Report

November 14, 2001

RBG-45870

RBF1-01-0258

Page 2 of 2

cc: U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

NRC Senior Resident Inspector
P. O. Box 1050
St. Francisville, LA 70775

INPO Records Center
700 Galleria Parkway
Atlanta, GA 30339-3064

Mr. Jim Calloway
Public Utility Commission of Texas
1701 N. Congress Ave.
Austin, TX 78711-3326

Dottie Sherman
American Nuclear Insurers
29 South Main Street
West Hartford, CT 06107

DOCKET NO. 50/458
RIVER BEND STATION

DATE November 14, 2001
COMPLETED BY Danny H. Williamson
TITLE Sr. Licensing Specialist
TELEPHONE 225-381-4279

PAGE 1 OF 2

OPERATING STATUS

1. REPORTING PERIOD: October 2001
2. MAXIMUM DEPENDABLE CAPACITY (MWe-Net): 936
3. DESIGN ELECTRICAL RATING (MWe-Net): 936

	<u>MONTH</u>	<u>YEAR TO DATE</u>	<u>CUMULATIVE</u>
4. NUMBER OF HOURS REACTOR WAS CRITICAL	<u>451.6</u>	<u>6735.8</u>	<u>109911.5</u>
5. HOURS GENERATOR ON LINE	<u>409.7</u>	<u>6657.2</u>	<u>106300.5</u>
6. UNIT RESERVE SHUTDOWN HOURS	<u>0</u>	<u>0</u>	<u>0</u>
7. NET ELECTRICAL ENERGY GENERATED (MWH)	<u>328,272</u>	<u>6,341,650</u>	<u>94,122,781</u>

UNIT SHUTDOWNS

<u>NUMBER</u>	<u>DATE</u>	<u>TYPE</u>	<u>DURATION</u>	<u>SHUTDOWN METHOD</u>	<u>REASON</u>	<u>CAUSE / CORRECTIVE ACTIONS</u>
01-02	011001	S	245.9 hrs.	4	C	Refueling outage no. 10
01-03	011011	S	1.1 hrs.	1	B	Scheduled main turbine testing (reactor remained critical)
01-04	011026	S	88.4 hrs.	2	B	Planned outage for replacement of reactor recirc pump seals

LEGEND:**TYPE:**

F - Forced
S - Scheduled

SHUTDOWN METHOD:


1 - Manual
2 - Manual trip / scram
3 - Automatic trip / scram
4 - Continuation
5 - Other (explain)

REASON:

A - Equipment failure (explain)
B - Maintenance or Test
C - Refueling
D - Regulatory restriction
E - Operator training / License Exam
F - Administrative
G - Operational error (explain)
H - Other (explain)

NOTES:

1. Please note that the initial phase of a power uprate modification has been installed at River Bend Station. A change in the maximum reactor feedwater flow was completed on October 24, 2000, resulting in a higher electrical output. The operating pressure of the reactor was increased as planned in the refueling outage completed on October 11, 2001. Until completion of appropriate tests and calculations, River Bend Station will continue to use the existing maximum dependable capacity.
2. There were no challenges to the reactor safety relief valves in October.



Danny H. Williamson