

Region I  
NMSS Licensee Event Report

License No. 07-28762-02G

Docket No. 03002988

MLER-RI 2002-006

LICENSEE: AGILENT TECHNOLOGIES

EVENT DESCRIPTION NOTICE OF GENERAL LICENSE DEVICES WITH HIGH REMOVABLE ACTIVITY

EVENT DATE 1-02 REPORT DATE 2-1-02

1. REPORTING REQUIREMENT

- |  |   |
|--|---|
| <input type="checkbox"/> 10 CFR 20.2201 Theft or Loss        | <input type="checkbox"/> 10 CFR 35.33 Misadministration |
| <input type="checkbox"/> 10 CFR 20.2203 30 Day Report        | <input type="checkbox"/> License Condition              |
| <input type="checkbox"/> 10 CFR 30.50 Report                 |   |
| <input checked="" type="checkbox"/> Other <u>10 CFR 31.5</u> |   |

2. REGION I RESPONSE

- |   |                                       |
|---|---------------------------------------|
| <input type="checkbox"/> Immediate Site Inspection                    | Inspector/Date _____                  |
| <input type="checkbox"/> Special Inspection                           | Inspector/Date _____                  |
| <input type="checkbox"/> Telephone Inquiry                            | Inspector/Date _____                  |
| <input checked="" type="checkbox"/> Preliminary Notification          | <input type="checkbox"/> Daily Report |
| <input checked="" type="checkbox"/> Information Entered on the RI Log |                                       |
| <input checked="" type="checkbox"/> Review at Next Routine Inspection |                                       |
| <input type="checkbox"/> Report Referred to _____                     |                                       |

3. REPORT EVALUATION

- |  |   |
|--|---|
| <input checked="" type="checkbox"/> Description of Event   | <input checked="" type="checkbox"/> Corrective Actions                        |
| <input checked="" type="checkbox"/> Levels of RAM Involved | <input type="checkbox"/> Calculation Adequate                                 |
| <input type="checkbox"/> Cause of Event                    | <input type="checkbox"/> Letter to Licensee Requesting Additional Information |

4. SPECIAL INSTRUCTIONS OR COMMENTS

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Completed By: Bates Ulbrich Date 2/4/02

Reviewed By: [Signature] Date 2/5/2002

RECEIVED  
REGION 1

 **Agilent Technologies**  
2850 Centerville Road  
Wilmington, DE 19808

2002 FEB -1 PM 2: 59

Division of Nuclear Materials Safety  
U.S. Nuclear Regulatory Commission  
Region I  
475 Allendale Road,  
King of Prussia, PA 19406

Re: Notice of General License devices with high removable activity (NRC License 07-28762-02G)

January 30, 2002


Dear Sir or Madam,

Per the requirements of 10 CFR 31.5, I am notifying your office of two general license devices from which we have obtained removable activity wipes in excess of 0.005  $\mu\text{Ci}$ . One cell (serial number L6846) was returned from an overseas customer and the other (serial K0640) was returned from a U.S. customer. The U.S. customer will be contacted for usage information. The cells were evaluated by support engineering and their dispositions are identified below. I will notify the cell supplier of the high wipes.

<u>Serial #</u>	<u>Model #</u>	<u>Activity (<math>\mu\text{Ci}</math>)</u>	<u>Disposition</u>
L6846	19233	0.009	To be disposed of
K0640	19233	0.129	To be disposed of

Please contact me at 302-633-8262 if there are any questions.

Thank you,

  
David S. Bennett  
Radiation Safety Officer