

Entergy Operations, Inc. River Bend Station

River Bend Station 5485 U.S. Highway 61 P. O. Box 220 St. Francisville, LA 70775 Tel 225 336 6225 Fax 225 635 5068

Rick J. King Director Nuclear Safety Assurance

January 14, 2002

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D. C. 20555

Subject:

Monthly Operating Report

River Bend Station Docket No. 50-458 License No. NPF-47

File No.:

G9.5, G4.25

RBG-45899 RBF1-02-0010

Ladies and Gentlemen:

In accordance with River Bend Station Technical Specification 5.6.4, enclosed is the Monthly Operating Report for December 2001.

Sincerely,

RJK/dhw

enclosure

IFAU

Monthly Operating Report January 14, 2002 RBG-45899 RBF1-02-0010 Page 2 of 2

cc: U. S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, TX 76011

> NRC Senior Resident Inspector P. O. Box 1050 St. Francisville, LA 70775

INPO Records Center 700 Galleria Parkway Atlanta, GA 30339-3064

Mr. Jim Calloway Public Utility Commission of Texas 1701 N. Congress Ave. Austin, TX 78711-3326

Dottie Sherman American Nuclear Insurers 29 South Main Street West Hartford, CT 06107

DOCKET NO. 50/458 RIVER BEND STATION

DATE January 14, 2002

COMPLETED BY Danny H. Williamson

TITLE Sr. Licensing Specialist

TELEPHONE 225-381-4279

PAGE _1 OF _2

OPERATING STATUS

1. REPORTING PERIOD: December 2001

2. MAXIMUM DEPENDABLE CAPACITY (MWe-Net): 936

3. DESIGN ELECTRICAL RATING (MWe-Net): 936

YEAR TO **CUMULATIVE** MONTH DATE 4. NUMBER OF HOURS REACTOR WAS CRITICAL 744.0 8199.8 111375.5 744.0 8121.2 107764.5 5. HOURS GENERATOR ON LINE 0 6. UNIT RESERVE SHUTDOWN HOURS 0 0 7. NET ELECTRICAL ENERGY GENERATED (MWH) 748,489 7,811,816 95,592,947

UNIT SHUTDOWNS

NUMBER	DATE	TYPE	DURATION	SHUTDOWN METHOD	REASON	CAUSE / CORRECTIVE ACTIONS
(none)						

LEGEND:

TYPE:

F - Forced

S - Scheduled

SHUTDOWN METHOD:

1 - Manuai

2 - Manual trip / scram

3 - Automatic trip / scram

4 - Continuation

5 - Other (explain)

REASON:

A - Equipment failure (explain)

B - Maintenance or Test

C - Refueling

D - Regulatory restriction

E - Operator training / License Exam

F - Administrative

G - Operational error (explain)

H - Other (explain)

NOTES:

- Please note that a power uprate modification has been installed at River Bend Station. A
 change in the maximum reactor feedwater flow was completed on October 24, 2000,
 resulting in a higher electrical output. The operating pressure of the reactor was increased in
 the refueling outage completed on October 11, 2001. Until completion of appropriate
 calculations, River Bend Station will continue to use the existing value for maximum
 dependable capacity.
- 2. There were no challenges to the reactor safety relief valves in December.

Danny H. Williamson