



February 19, 2002

AEP:NRC:2455

Docket No: 50-316

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Stop O-P1-17
Washington, DC 20555-0001

Donald C. Cook Nuclear Plant Unit 2
STEAM GENERATOR TUBE INSERVICE INSPECTION REPORT

Indiana Michigan Power Company, the licensee for Donald C. Cook Nuclear Plant (CNP) Unit 2, is submitting this letter in accordance with Technical Specification 4.4.5.5.a, to notify the Nuclear Regulatory Commission that, based upon eddy current inspection results during CNP's Unit 2 Cycle 13 steam generator inspection, no tubes required repair (plugging) in steam generators 21, 22, 23, or 24.

There are no new commitments in this submittal. Should you have any questions, please contact Mr. Gordon P. Arent, Manager of Regulatory Affairs, at (616) 697-5553.

Sincerely,

A handwritten signature in black ink, appearing to read 'S. A. Greenlee'.

S. A. Greenlee
Director of Nuclear Technical Services

/jen

c: K. D. Curry
J. E. Dyer
MDEQ – DW & RPD
NRC Resident Inspector
R. Whale

A047