

February 22, 2002

Arthur Kleinrath, Project Manager
U. S. Department of Energy
Grand Junction Office
2597 B 3/4 Road
Grand Junction, CO 81503

SUBJECT: REVIEW OF 2001 TITLE II ANNUAL SITE INSPECTION REPORT

The U.S. Nuclear Regulatory Commission (NRC) staff has reviewed "2001 Annual Site Inspection and Monitoring Compliance Report for Title II Disposal Sites," dated January 24, 2002. Based on this review, we conclude that the inspections and the routine actions that are being performed are acceptable.

The staff notes that a large number of photographs were provided for the Sherwood site to document baseline conditions. We consider this to be an excellent procedure and suggest that the first inspection of any new sites in the future should include such extensive photographic documentation.

This review was performed by Ted Johnson. If you have any questions, please contact Mr. Johnson at (301) 415-6658.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/NRC/ADAMS/index.html> (the Public Electronic Reading Room).

Sincerely,

/RA/c/GSJ

Melvyn Leach, Chief
Fuel Cycle Licensing Branch
Division of Fuel Cycle Safety
and Safeguards
Office of Nuclear Material Safety
and Safeguards

Arthur Kleinrath, Project Manager
 U. S. Department of Energy
 Grand Junction Office
 2597 B 3/4 Road
 Grand Junction, CO 81503

SUBJECT: REVIEW OF 2001 TITLE II ANNUAL SITE INSPECTION REPORT

The U.S. Nuclear Regulatory Commission (NRC) staff has reviewed "2001 Annual Site Inspection and Monitoring Compliance Report for Title II Disposal Sites," dated January 24, 2002. Based on this review, we conclude that the inspections and the routine actions that are being performed are acceptable.

The staff notes that a large number of photographs were provided for the Sherwood site to document baseline conditions. We consider this to be an excellent procedure and suggest that the first inspection of any new sites in the future should include such extensive photographic documentation.

This review was performed by Ted Johnson. If you have any questions, please contact Mr. Johnson at (301) 415-6658.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/NRC/ADAMS/index.html> (the Public Electronic Reading Room).

Sincerely,

/RA/c/GSJ

Melvyn Leach, Chief
 Fuel Cycle Licensing Branch
 Division of Fuel Cycle Safety
 and Safeguards
 Office of Nuclear Material Safety
 and Safeguards

DISTRIBUTION: FCLBr/f ACNW CNWRA CCAIN/RIV

ADAMS Accession No.: ML020530418

Document Name: G:\FCLB\Uranium Recovery Section\T2ANRPO2.wpd

OFC	FCLB	C	FCLB		FCLB			
NAME	TJohnson*		GJanosko*		Mleach for			
DATE	02/19/02		02/19/02		02/21/02			

*See previous concurrence

OFFICIAL RECORD COPY