

North Atlantic Energy Service Corporation P.O. Box 300 Seabrook, NH 03874 (603) 474-9521

The Northeast Utilities System

February 13, 2002

Docket No. 50-443

NYN-02014

United States Nuclear Regulatory Commission Attn.: Document Control Desk Washington, DC 20555-0001

Seabrook Station 2001 Annual Report of Removable Contamination from Sealed Source or Fission Detector

Seabrook Station Technical Specification 4.7.8.3 requires a report be prepared and submitted if sealed source or fission detector leakage tests reveal the presence of greater than or equal to 0.005 microCurie of removable contamination. In accordance with this requirement, North Atlantic Energy Service Corporation hereby reports that during 2001, there were no leaking sources. A Second of the secon

Should you have any questions, please contact Mr. William T. Cash, Manager - Health Physics, at (603) 773-7315.

Translation (*) in parameter production of the production of the control of the con

Very truly yours,

NORTH ATLANTIC ENERGY SERVICE CORP.

ency a sing making at an electric

James M. Peschel

Manager – Regulatory Programs

cc: H. J. Miller, NRC Region I Administrator

ele light extra legisted in the egist.

G.F. Wunder, NRC Project Manager, Project Directorate I-2

G.T. Dentel, NRC Senior Resident Inspector

ાં તમાનું આ ભાગ તમાં સુજ્યાલમાં ચું માર્ગ કે માં કુલ્લાનું ઉત્તર પ્રાથમિક ભાગમાં કરે સિંહા તમાં કુલમાં છે. આ આ તમાનું આ ભાગ તમારું તમારું સુરાત કર્યા કુલ કુલ કે માં કહેલા અપ્રોગમ સુરાત કિંદ ભાગમાં કરે સિંહા તમાં કુલમાં છે and the companies from again, and conjugate was a graph of the matter and the matter of the first of the first