

SUE W. KELLY
 10111 United S. Blvd. Vienna
 COMMITTEE ON
 TRANSPORTATION AND INFRASTRUCTURE
 SUBCOMMITTEE ON SURFACE TRANSPORTATION
 SUBCOMMITTEE ON WATER RESOURCES
 AND ENVIRONMENT
 COMMITTEE ON SMALL BUSINESS
 CHAIRMAN, SUBCOMMITTEE ON REGULATORY
 BURDEN AND PAPERWORK REDUCTION
 COMMITTEE ON BANKING AND
 FINANCIAL SERVICES
 SUBCOMMITTEE ON FINANCIAL INSTITUTIONS
 AND CONSUMER CREDIT
 SUBCOMMITTEE ON HOUSING AND
 COMMUNITY OPPORTUNITY
 ASSISTANT MAJORITY WHIP

Congress of the United States
House of Representatives
 Washington, DC 20515-3219

Please Return To:
 1122 LINDSEY BLDG OFFICE BUILDING
 WASHINGTON, DC 20515
 (202) 225-5441
 21 OLD MAM STREET, SUITE 8205
 FORT LEE, NEW YORK 12524
 (518) 897-5200
 118 RIVER CHURCH DRIVE
 Mt. Kisco, New York 10549
 (518) 241-6340

September 1, 2000

Mr. Thomas Bliley, Chairman
 House Committee on Commerce
 2125 Rayburn House Office Building
 Washington, DC 20515

Dear Chairman Bliley,

I am writing to you concerning a report released August 31st by the NRC's Office of Inspector General outlining disturbing deficiencies in the oversight responsibilities of NRC management at the Indian Point 2 nuclear power plant in Buchanan, NY.


The report concluded that the NRC had in its possession, but failed to thoroughly review, a 1997 inspection report containing information that could have prevented a February 15th steam generator leak at the plant that threatened the community's safety.


The Inspector General's office reported that the NRC gave only cursory review to a 1997 inspection report concerning the plant and that a junior engineer was discouraged from obtaining any additional information after concluding that the plant's operator failed to provide enough information in its request to postpone a 1999 inspection. An official from the IG's office stated that had the NRC looked at the inspection more thoroughly, "they would have seen the steam generator was nearly cracked all the way through." In addition, the IG's report concluded that the NRC did not view steam generator issues at Indian Point 2 as significant.

Mr. Chairman, what occurred at Indian Point 2 is a glaring example of what can go wrong at any nuclear power plant when there exists a culture of neglect within the NRC. Surely, this is not an isolated case. Communities surrounding other nuclear plants nationwide may not be getting the protection they are entitled to.

The NRC's mission is to protect the public. Its ability to do that has been severely called into question. Therefore, I respectfully request that your committee convene congressional hearings as soon as possible to explore the issue of poor NRC oversight at Indian Point 2 and at nuclear power plants across the country.

Sincerely,


 Sue Kelly
 Member of Congress


 31