CORR: 00-0103-REVISED

CORR: 00-0103-REVISED

200 JUL 12 PH 3:30

## COMMISSION CORRESPONDENCE

Correspondence Response Sheet

Approve with edits.

Date:

July 12, 2000

To:

Chairman Meserve

Commissioner Dicus ~

Commissioner Diaz

Commissioner McGaffigan Commissioner Merrifield

From:

Annette Vietti-Cook, Secretary

Subject:

Letter to Representative Sue W. Kelly concerns the safety

of operations at the Indian Point 2 plant

ACTION: Please comment/concur and respond to the Office of the

07/17/00

Secretary by:

Time:

C.Q.B.

Day:

Wednesday

Date:

July 1/9, 2000

Comment:

RESPONSE REFERS TO OIG BRIEFING ON JULY 21.

Contact:

George Wunder, EDO/NRR

415-1494

Entered in STARS Tracking System Yes Wo



## UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

The Honorable Sue W. Kelly U.S. House of Representatives Washington, D.C. 20515-3219

Dear Congresswoman Kelly:

I am responding to your letters of May 26, 2000, and June 28, 2000, in which you expressed continued concern about operation of the Indian Point Nuclear Generating Unit No. 2 (IP2). You specifically expressed concern about the steam generator tube failure at IP2 on February 15, 2000, and about the efforts being undertaken by our Office of the Inspector General (OIG).

As you are aware from discussions with NRC staff, since the February 15, 2000, event, the plant's owner, Consolidated Edison Company of New York, Inc. (Con Ed), has inspected the tubes in all four steam generators. As a result of this inspection, Con Ed removed some tubes out of the service. Con Ed evaluated the tube inspection data and concluded in its Operational Assessment Report of June 2, 2000, that there is reasonable assurance that the tubes that have been left in service will maintain their structural integrity for 10 months of operation.

Ed has stated their intention to begin replacement of the steam generators by the end of the year. The NRC staff is reviewing Con Ed's report and, based on this review, will determine whether or not continued operation of IP2 with the current steam generators poses an undue risk to public health and safety. Our Regional staff are also continuing their inspection activities in order to ensure that all appropriate corrective actions have been completed.